

SMRT Accident Vehicle Repair Estimates

Section A - Accident Details					
Registration Number	SG5769X				
Case Reference Number	BUS/01/21/5044				
Registration Date	18/8/2016				
Company Type	SMRT Buses Ltd				
Make	MAN				
Model	A95				
Name of Driver	Lim Chye Kiosk				
Type of Accident	Side Swipe				
Accident Date and Time	15/1/2021 8:28 AM				
Accident Reported Date and Time	15/1/2021 9:45 AM				
Is Surveyor Required?	Yes				
Survey by					
Vehicle is Towed Back?	No				
Towed Back Date and Time					
Replacement Vehicle issued?	No				
Job Card Number	24109591				
Special Instruction to ARC,if any	SG5769X - LEFT FRONT PORTION SMU8018H (TP) - INSURED WITH AIG				
Prepared Date and Time	27/1/2021 3:39 PM				
Chassis Number	WMAA95ZZ4G7003240				
Mileage					
Work Shop					
Repair Completion Date and Time					

	Section B - Summary of Rep	air Estimates			
Summary of Repair Estimates					
	Quotation from ARC	Adjusted by Surveyor, if applicable			
Total Labour Cost	\$530.00	\$265.00			
Total Spray Cost	\$432.00	\$262.00			
Total Spare Part Cost	\$0.00	\$0.00			
Total Other Cost	\$0.00	\$0.00			
TOTAL COST	\$962.00	\$527.00			
Lump Sum Total	\$0.00	\$0.00			
Number of Repair Days	2.0	1.0			
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)			
ARC / Surveyor Sign Off Date	27/01/2021 3:39 PM	27/01/2021 4:18 PM			
Signature	8	Sun Pin			
Remarks					

Section C - Quotation and Accident Invoice Details					
Quotation Number		Invoice Number			
Quotation Date		Invoice Date			
Invoice Amount		Prepared Date			

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 10/02/2021
User ID : CatherineLee



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated: 10/02/2021

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labou	ır Works								
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REPAIR LH FRONT PORTION			\$530.00				\$265.00		
Total Labour			\$530.00				\$265.00		
Part 2 - Spray	Painting & Pa	nel Beating Rela	ted Works						
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
TO PUTTY & R	ESPRAY			\$432.00	\$432.00				
Total Spray Painting & Panel Beating			\$432.00	\$432.00				\$262.00	
Part 3 - Other	Costs - Accid	ent and Accident	Repair Related Expen	se					
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare	Parts / Materi	al Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to finel approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: