

ASS. REC. BY: Sun Pin

REF:

NTUC NS/INC21001387/Qvf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMA 4342C

Policy No. _____

Claims No. MT/1118406-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMB 1061 Yr Regn: 07/10/2008Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes benz OC500 c.c. 11967Colour: Black. A/C: Insured / Std / NI / NASp. Reading: 981661 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WEB63442021000667Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 275 / 70 R 22.5R: 275 / 70 R 22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 22/1/21 D.O.I. 28/01/2021Survey held at SMRTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Pending Workshop GIA

15/3/21 LS \$3700 confirmed by email (Red 4355.70,54%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 17/3/21-Typist

Report Format: TPLump Sum / L.B.L. : LS \$3700Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/01/2021


User ID : BoonChewTay

Section A - Accident Details

Registration Number	SMB10G
Case Reference Number	BUS/01/21/1041
Registration Date	7/10/2008
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Teyu Soin Boon
Type of Accident	Head to Rear
Accident Date and Time	22/1/2021 2:49 PM
Accident Reported Date and Time	22/1/2021 3:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB10G - REAR RIGHT PORTION SMA4342C (TP) - INSURED WITH NTUC
Prepared Date and Time	28/1/2021 2:17 PM
Chassis Number	WEB63442021000067
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$602.00	\$0.00
Total Spare Part Cost	\$2,359.60	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,551.60	\$0.00
Lump Sum Total	\$4,550.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	28/01/2021 2:33 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/01/2021

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	1060
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$602.00	432
Total Spray Painting & Panel Beating	\$602.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
009367	Body	6013	DOOR, REAR, ENGINE, F OR MB OC500 BUS	1.00	\$2,484.00	100.00	\$0.00	Repair	X R.
009366	Body		BUMPER, REAR, FIBREGLASS, FOR MB OC500 BUS	1.00	\$1,863.00	10.00	\$1,676.70	Replace	/ CRU
009369	BODY RH		COVER, LAMP, REAR, RH, FOR MB OC500 BUS	1.00	\$1,242.00	10.00	\$1,117.80	Replace	/ CRU
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	/ CRU
			STICKER SG LOVE	1.00	\$75.00	0.00	\$75.00	Replace	/ CRU
			STICKER 60KM/H	1.00	\$5.00	0.00	\$5.00	Replace	/ CRU
Total					\$5,744.00		\$2,949.50		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 3 days.

L/S
After paint photo
Sun Pm (L/S)
28/01/2021
TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SMB10G
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jan 2021
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	OC500LE1830H
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	45796600138357
Chassis No.:	WEB63442021000067
Maximum Power Output:	-
Open Market Value:	\$319,038.00
Original Registration Date:	07 Oct 2008
First Registration Date:	07 Oct 2008
Transfer Count:	0
Actual ARF Paid:	\$15,952.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 29 Jan 2021

OK