

ASS. REC. BY:

REF:

CS/AH21001393/Rvd3

2844

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

YP 439M

at Workshop m/s

NGEE NGEE NGEE

of

PANDAN LOOP BLK 3

Insured:

AH

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

S/K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

YP 439M

Yr Regn:

2015/Dec

Type: M.Car / M.Cycle / Bus / Van / ☒ Corp / Taxi / Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI CANTER FEB 21ER c.c 2998

Colour

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

48733

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

FEB 21ER 10703

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: In order / ☒ Jammed / Leaked / Burnt orBrake: In order / ☒ Jammed / Leaked / Burnt orModi: ☒ M / S/Rim / STD A/Rim or

Tyre Size:

F:

195/85R15

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or .

Front

Rear

R/Bal.

7

mm

R/Bal.

7/7

mm

L/Bal.

7

mm

L/Bal.

7/7

mm

D.O.A.

02/01/2021

D.O.I.

29/01/2021

Survey held at

NGEE NGEE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Unit - 44K

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2) 1/2/21-Typist

Rep. Format: DAR

Lump Sum / L.S. (\$ _____)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$ _____)



Interview (\$ _____)



Tech. Invs (\$ _____)



Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/01/2021 14:03 (SGT)
Date of Accident	02/01/2021 15:05 (SGT)
Exact Location of Accident	291 Yishun Street 22, Singapore 760291
Additional Location Information	PARKING AREA
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP439M
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	EDMUND VEHICLE RENTAL PTE LTD
Company Reg No	2XXXXXX244G
Email Address	edmundevr@gmail.com
Mobile Phone No	(Phone) +65-62503339
Alternative Phone No	(Office) +65-62503339

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Fuso
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	5112254195-01
Cover Note Number	-

DRIVER

Name of Driver	CHEN FENG
Passport No/FIN	GXXXX193T
Date Of Birth	01/10/1994
Occupation	Outdoor



ing Pass	04/11/2019
erience	1 YEAR AND 2 MONTHS
Number	Male
Phone Number	(Phone) +65-83324272
ail Address	-
dress	edmundevr@gmail.com
Address complement	279 BALESTIER ROAD #02-27 BALESTIER POINT
Postcode	-
Is the driver the policyholder?	329727
If No, Relationship of the Driver with the Insured	No
Does Driver Own Other Vehicles?	Hirer
Vehicle Registration Number of Other Vehicle Owned by Driver	No
Insurance Company of Other Vehicle Owned by Driver	-
	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	AFTER - RAIN
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED ; REMARKS: TYPE OF ACCIDENT PLEASE REFER TO ATTACHED AND ATTACHED STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	GBC6132Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	TOH HONG TEE
NRIC No	SXXXX456G
Contact Number	(Phone) +65-96179007
Address	-
Address complement	-
Postcode	-

.pany Name
.nage
operty damaged in accident
senger (Including Driver)

-
REFER TO ATTACHED
REFER TO ATTACHED
-


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

BLK 291 YISHUN STREET, 22 CARPARK LOADING/UNLOADING BAY

A → 4P439M

B → GBC61322



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I (4P439M) WAS DRIVING THIS VEHICLE. ON 02/01/2021 @
AROUND 3PM. MY VEHICLE WAS PARKED STATIONERY AT 291 YISHUN
STREET 22 CARPARK. SUDDENLY GBC61322 REVERSED AND
KNOCKED MY FRONT VEHICLE BUMPER.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	244G

Vehicle No.:	YP439M
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2021
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	4P10B90434
Chassis No.:	FEB21EA10703
Maximum Power Output:	-
Open Market Value:	\$30,253.00
Original Registration Date:	07 Dec 2015
First Registration Date:	07 Dec 2015
Transfer Count:	1
Actual ARF Paid:	\$1,513.00


PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

COE Expiry Date:	06 Dec 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$13,381.00
COE Rebate Amount:	\$6,489.00
Total Rebate Amount:	\$6,489.00

The information contained herein is correct as at 31 Jan 2021

OK

White





Merimen e-Claims



Used 2015 Mitsubishi Fuso Canter



PARF/COE Re

art.com/used_cars/info.php?ID=960084&DL=2976

► Mitsubishi Fuso Canter FEB21

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price	\$51,800	Lifespan	28-Dec-2035
Depreciation	\$10,550 /yr View models with similar depre	Reg Date	29-Dec-2015 (4yrs 10mths 27days COE left)
Mileage	N.A.	Manufactured	2015
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$2,305 as of today (change)	OMV	\$29,568
COE	\$4,694	ARF	\$1,479
Engine Cap	2,998 cc	No. of Owners	2
Curb Weight	2,260 kg		
Type of Vehicle	Truck		

Features

View specs of the Mitsubishi Fuso Canter (2015)

D



(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched (07)Deformed
(08)Shifted (09)Buckled (10)Broken (11)Necessary (12)Missing (13)Torn
(14)Unconfirmed (15)Not Working

VAN / LORRY (Frt)

(1)Plates / (2)Repair (3)Check P
(4)Not Consistent (5)

Front Portion

Vehicle No:

4P439M

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	see R		
2001	991477	Frt Bumper Upper			
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side			
1006	991325	Frt Bumper Bracket			
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1007	995100	Frt LH Bumper Fog Lamp Cover			
1008	991355	Frt RH Bumper Fog Lamp Cover			
1009	995079	Frt LH Bumper Fog Lamp			
1010	995080	Frt RH Bumper Fog Lamp			
1011	991793	Frt Grille			
1012	991328	Frt Grille Emblem			
2006	990247	Frt Grille Sticker			
1003	991799	Frt Grille Chrome Moulding	see R		
2007	991891	Frt Panel			
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1013	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel LH	see R		
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH	CM		
2015	995246	Frt Signal Lamp RH			
1014	995153	Frt LH Headlamp Assy			
1015	991821	Frt RH Headlamp Assy			
1016	995088	Frt LH Side Lamp			
1017	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1018	992140	Frt Wiper Arm			
1019	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1020	995045	Wiper Panel Garnish			
1021	992093	Frt Windscreen			
1022	992097	Frt Windscreen Rubber			
1023	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1024	991019	ERP Bracket			
1025	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay			
1026	992013	Frt Support Panel			
1027	990248	Bonnet			
1028	990287	Bonnet Lock			
1029	990273	Bonnet Hinge			
1030	990305	Bonnet Rubber			
1031	990119	Air Con Condenser			
1032	990122	Air Con Fan Assy			
1033	990149	Air Con Liquid Pipe			
1034	995066	Air Con Receiver Drier			
1035	995074	Radiator			
1036	992738	Radiator Cowling			
1037	992742	Radiator Fan Assy			
1038	992758	Radiator Hose Top			
1039	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1040	994431	Power Steering Cooler Pipe			
1041	990151	Air Duct			
1042	990070	Air Cleaner Assy			
1043	990219	Battery			
1044	990223	Battery Bracket			

NAC	INC	Item	CON	AC	Qty
1035	991011	Engine Under Cover			
1036	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1037	991520	Frt LH Chassis Member			
1038	991520	Frt RH Chassis Member			
1039	990728	Frt Vertical Cross Member			
1040	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1041	990427	Brake Master Pump Assy			
1042	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1043	994483	Steering Wheel Airbag			
1044	994485	Steering Wheel Airbag Sensor			
1045	990029	Airbag Control Unit			
1046	991922	Frt RH Seat Belt Assy			
1047	995182	Frt LH Seat Belt Assy			
1048	990753	Dashboard Assy			
1049	992282	Glove Box Cover			
1050	992281	Glove Box Compartment			
1051	995070	Frt LH Fender			
1052	995072	Frt LH Fender Inner Panel			
1053	991740	Frt LH Fender Inner Shield			
1054	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1055	995170	Frt LH Wheel Rim			
1056	995065	Frt LH Tyre			
1057	995071	Frt RH Fender			
1058	991739	Frt RH Fender Inner Panel			
1059	991740	Frt RH Fender Inner Shield			
1060	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1061	992087	Frt RH Wheel Rim			
1062	995065	Frt RH Tyre			
1063	995326	Frt LH Door			
1064	995140	Frt LH Door Protector			
1065	995104	Frt LH Door Hinge			
1066	995142	Frt LH Door Wing Mirror			
1067	995103	Frt LH Door Glass			
1068	991595	Frt LH Door Glass Regulator			
1069	991596	Frt LH Door Glass Regulator Motor			
1070	991662	Frt LH Door Rubber			
1071	991636	Frt LH Door Outer Handle			
1072	991617	Frt LH Door Inner Trim Board			
1073	995327	Frt RH Door			
1074	991654	Frt RH Door Protector			
1075	991601	Frt RH Door Hinge			
1076	991685	Frt RH Door Wing Mirror			
1077	991584	Frt RH Door Glass			
1078	991595	Frt RH Door Glass Regulator			
1079	991596	Frt RH Door Glass Regulator Motor			
1080	991662	Frt RH Door Rubber			
1081	991636	Frt RH Door Outer Handle			
1082	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1083	995053	Wiper Washer Tank			
1084	990247	Sticker			

3 days

No of Items:

Assessor: