

12/17/2020

REF: CS3/CTI21001396/R1td3

Special Instruction:

ASS. REC. BY:

Surveyor: RASUL

ASSIGNMENT (Office)

From (Person): ADELINE CHNG

of CTI

Date/Time: 29/01/2021@10.48AM

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 7413S

Insured: GBF 5497L

at Workshop m/s KOK WANG CAR GROOMING

Tel: 9183 9633

of NO. 1 SOON LEE STREET# 06-40

Policy No:

Claim No: SNM21D200549/C02/GBE5497L/CHNGPW

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 26/01/2021

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 11.21PM@29/01/21

Person Contacted: MR. PAUL

Vehicle IN OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SMD 7413S-X
	GBF 5497L-X