



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC20012018/Eqf3e2-1	
			Date: 01/02/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XB 9299B		Veh. Inspected	SFN 4356C
Policy No.			Coverage (\$)	0.00
Claim No.	20/20/20/VC05/023842		Excess (\$)	0.00
Assign From	ONG LI LI		Assign Date	12/01/2021
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C200 COUPE		c.c	1991
Engine No.	HIDDEN		Year of Reg.	2017
Chassis No.	WDD2053422F489998		Colour	WHITE
Odometer	56315 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/40 R18	CONTINENTAL	5 mm	
L/H Front Tyre	215/40 R18	CONTINENTAL	5 mm	
R/H Rear Tyre	215/40 R18	CONTINENTAL	5 mm	
L/H Rear Tyre	215/40 R18	CONTINENTAL	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/10/2020		Inspection Date	04/11/2020
Survey held at	SKM GARAGE & TRADING LLC 10 KAKI BUKIT ROAD 2 #03-22 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	