



## SMRT Accident Vehicle Repair Estimates

|   |
|---|
| <b>SMRT Automotive Services Pte Ltd</b>           |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |


Date Generated : 28/01/2021

User ID : GohKK2

### Section A - Accident Details

|                                    |  |
|------------------------------------|--|
| Registration Number                | SMB1425L   |
| Case Reference Number              | BUS/01/21/7025   |
| Registration Date                  | 8/7/2014   |
| Company Type                       | SMRT Buses Ltd   |
| Make                               | MAN  |
| Model                              | MAN NL320F(A22)  |
| Name of Driver                     | Mohd Hafez Bin Mohamed Akhir                                     |
| Type of Accident                   | Head To Side   |
| Accident Date and Time             | 22/1/2021 4:34 PM  |
| Accident Reported Date and Time    | 22/1/2021 6:45 PM  |
| Is Surveyor Required?              | Yes  |
| Survey by                          |  |
| Vehicle is Towed Back?             | No   |
| Towed Back Date and Time           |  |
| Replacement Vehicle issued?        | No   |
| Job Card Number                    |  |
| Special Instruction to ARC, if any | SMB1425L - LEFT REAR PORTION<br>SFA1778G (TP) - INSURED WITH AIG |
| Prepared Date and Time             | 28/1/2021 12:58 PM   |
| Chassis Number                     | WMAA22ZZXE7002139  |
| Mileage                            |  |
| Work Shop                          |  |
| Repair Completion Date and Time    |  |

### Section B - Summary of Repair Estimates

| Summary of Repair Estimates  |   |                                     |
|------------------------------|---|-------------------------------------|
|                              | Quotation from ARC  | Adjusted by Surveyor, if applicable |
| Total Labour Cost            | \$1,060.00  | \$0.00                              |
| Total Spray Cost             | \$708.00  | \$0.00                              |
| Total Spare Part Cost        | \$0.00  | \$0.00                              |
| Total Other Cost             | \$960.00  | \$0.00                              |
| <b>TOTAL COST</b>            | <b>\$2,728.00</b>   | <b>\$0.00</b>                       |
| <b>Lump Sum Total</b>        | <b>\$2,750.00</b>   | <b>\$0.00</b>                       |
| Number of Repair Days        | 3.0   |                                     |
| Prepared / Adjusted By       | Kok Khoon Goh   |                                     |
| ARC / Surveyor Sign Off Date | 28/01/2021 1:03 PM  |                                     |
| Signature                    |  | x                                   |
| Remarks                      |   |                                     |

### Section C - Quotation and Accident Invoice Details

|                  |  |                |  |
|------------------|--|----------------|--|
| Quotation Number |  | Invoice Number |  |
| Quotation Date   |  | Invoice Date   |  |
| Invoice Amount   |  | Prepared Date  |  |



## SMRT Accident Vehicle Repair Estimates

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 28/01/2021

User ID : GohKK2

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

| Job Scope   | Quotation from AR | Adjusted by Surveyor, if applicable |
|---|-------------------|-------------------------------------|
| TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. | \$1,060.00        | <del>530</del> 530                  |
| <b>Total Labour</b>   | <b>\$1,060.00</b> |                                     |

#### Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope   | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS | \$708.00           | 538                                 |
| <b>Total Spray Painting &amp; Panel Beating</b>                     | <b>\$708.00</b>    |                                     |

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------|--------------------|-------------------------------------|
| ADVERTISEMENT STICKER    | \$960.00           |                                     |
| <b>Total Other Costs</b> | <b>\$960.00</b>    |                                     |

#### Part 4 - Spare Parts / Material Usage

| Part Number  | Portion | Stock Number | Part Name                                  | Quantity | List Price (\$)   | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|--------------|---------|--------------|--|----------|-------------------|--------------|------------------|--------------------|-------------------|
| 6010005      | BODY LH | A01001-CW561 | PANEL, SIDE: L11, FOR MAN A22 BUS          | 1.00     | \$1,092.50        | 100.00       | \$0.00           | Repair             | X R               |
| 6010060      | Body    | F01001-CW271 | COVER: REAR TAIL LAMP, LH, FOR MAN A22 BUS | 1.00     | \$974.70          | 100.00       | \$0.00           | Repair             | X R               |
| <b>Total</b> |         |              |  |          | <b>\$2,067.20</b> |              | <b>\$0.00</b>    |                    |                   |

#### Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number  | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|--------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| <b>Total</b> |         |              |           |          |               |              |                  |           |                |

Repair day - 2 days.

LIS

After paint photo.

Sun Pin (LKK)

28/01/2021

TP without prejudice

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: