

ASS. REC. BY:

REF: CS3/ASM21001402/R1qf3

Special Instruction:

Surveyor: RASULASSIGNMENT (Office)From (Person): Tan Jun Hong of AXA Date/Time: 29/1/2021 12:20 PM

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: JRC 6736 Insured: SHA 6049Xat Workshop m/s Dynasty Motor Pte Ltd Tel: 90996609of 50 Bukit Batok St 23 #01 - 24Policy No: _____ Claim No: S1M031JG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23.01.2021
(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 29-01-21 2.31P.M Person Contacted: JACKLYN Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	JRC 6736- ☒
	SHA 6049X - CS/FCI16009237/Ktbd1 DOA :13/05/2016