

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLC5619A (Insd veh)	Model:	SUBARU LEVORG 1.6 GT-S AWD CVT (A)
	EV9983D (TP veh)		
Date of Accident:	27/01/2021		

Global Sum Settlement	:	[] Yes	[X] No		
Repair Estimate	:	\$		3,773.41	
Final Repair Cost	:	\$		2,416.06	
Loss of Use	:	\$		180.00	3.00 days at \$60.00 per day
Rental (if any)	:	\$		0.00	days
LTA / GIA Search Fee	:	\$		2.00	
Others:	:	\$		0.00	
	:	\$			
Final Settlement Sum	:	\$		2,598.06	
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)					
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)			
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____			
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Optima Werkz Pte Ltd	:	\$ 2,598.06
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

18 Jun 2021

Date

**Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))**

