



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                          |                 |                            |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|-----------------|----------------------------|--|
| SOMPO INSURANCE SINGAPORE PL<br>50 RAFFLES PLACE #03-03<br>SINGAPORE LAND TOWERSINGAPORE 048623                                        |                                                                                          |                 | Ref: CS/SMO21001410/Kvf3e2 |  |
|                                                                                                                                        |                                                                                          |                 | Date: 18/03/2021           |  |
|                                                                                                                                        |                                                                                          |                 | Code: SMO                  |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                          |                 |                            |  |
| Insured Veh.                                                                                                                           | SLG 6853L                                                                                | Veh. Inspected  | SLT 158G                   |  |
| Policy No.                                                                                                                             | D20MTPV01016848                                                                          | Coverage (\$)   | 0.00                       |  |
| Claim No.                                                                                                                              | CMTD2100326/GPL                                                                          | Excess (\$)     | 0.00                       |  |
| Assign From                                                                                                                            | GRACE TEO                                                                                | Assign Date     | 29/01/2021                 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                          |                 |                            |  |
| Make & Model                                                                                                                           | HONDA SHUTTLE (A)                                                                        | c.c             | 1496                       |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                   | Year of Reg.    | 2020                       |  |
| Chassis No.                                                                                                                            | GK82101309                                                                               | Colour          | METALLIC GREY              |  |
| Odometer                                                                                                                               | 13532 KM                                                                                 | Steering        | IN ORDER                   |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                 | Modification    | SPORTS RIM                 |  |
| General                                                                                                                                | GOOD                                                                                     |                 |                            |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                          |                 |                            |  |
|                                                                                                                                        | Size                                                                                     | Make            | Balance                    |  |
| R/H Front Tyre                                                                                                                         | 205/50Z R16                                                                              | KUMHO           | 7 mm                       |  |
| L/H Front Tyre                                                                                                                         | 205/50Z R16                                                                              | KUMHO           | 7 mm                       |  |
| R/H Rear Tyre                                                                                                                          | 205/50Z R16                                                                              | KUMHO           | 7 mm                       |  |
| L/H Rear Tyre                                                                                                                          | 205/50Z R16                                                                              | KUMHO           | 7 mm                       |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                          |                 |                            |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.<br>DAMAGES SEE DETAILS.                                                         |                                                                                          |                 |                            |  |
| <b>5. General Information</b>                                                                                                          |                                                                                          |                 |                            |  |
| Accident Date                                                                                                                          | 28/01/2021                                                                               | Inspection Date | 01/02/2021                 |  |
| Survey held at                                                                                                                         | KGC WORKSHOP PTE LTD<br>176 SIN MING DRIVE, SIN MING AUTOCARE #02-04<br>SINGAPORE 575721 |                 |                            |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                          |                 |                            |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                          |                 |                            |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                          |                 |                            |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                          |                 | 2 Working Days             |  |