

12/01/2021

REF: CS/MSG21001423/d3

Special Instruction:

ASS. REC. BY:

ASSIGNMENT (Office)

SURVBY
Merimen

From (Person): MONICA CHUNG

of MSIG

Date/Time: 29/01/2021@4.52PM

Estimated Cost:

Bill to:

OD: ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMW 3631J

Insured: FT 8878E

at Workshop m/s EMPIRE IMAGE

Tel: 9742 5441

of NO 4 PANDAN LOOP (BLK 1/ BLK K)

Policy No: MSD/VMS/20-415920

Claim No: MSC/V/21-000054

Sum Insured:

Excess:

D.O.A. 27/01/2021

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 5.15PM@29/01/21

Person Contacted: KENNY

Vehicle: ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SMW 3631J-X
	FT 8878E-X