

CS3/LPC20007697/T1qf3 -1

ASS. REC. BY:

REF: CS3/LPC20007697/T1sf3

Special Instruction:

Surveyor: TAUFIKHASSIGNMENT (Office)

1/2/2021

From (Person): Gerald Poh

of

LPCDate/Time: 27/7/2020 1:13 PM

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBQ 8395UInsured: GBE 943Dat Workshop m/s M1 MotoringTel: 6743 7030of 411 Changi Road Singapore

Policy No:

Claim No: 19/20/20/VC00/023445

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/7/2020

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 27-7-20 2.19P.MPerson Contacted: Xiao LongVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	FBQ 8395U- <input checked="" type="checkbox"/>
	GBE 943D- <input checked="" type="checkbox"/>
	Received original document from Gerald on 1/2/2021.
* 01/7/21	Please return original document & photos to LPC.
02/7/21	Submit LS to LPC, 6 days (Ref # 2000, 317.)

6/5 \$4400
6 days

CS3/LPC 20007697/T19f3-1

ASS. REC. BY: Taughlin


REF:

LPC ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at (W/O) Trip m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

PRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: EGQR3954 Yr Regn: 2019, Dec
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda (B190X) c.c. 189
 Colour: Red / Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 4737 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: LWBP CL/A1 K1000431
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: W / S/Rim / STD A/Rim or _____
 Tyre Size: F: 110/70R17
 R: 146/70R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or IST
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. 27/7/2019 240
 Survey held at MI Workshop
 Des. of Damages: Ft / Rear / O/S / N/S / UIC / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No GIA

or/for 03/08/2020
 typist TYPIST
 Date/Time, File Return to?

☐ : Prel. Report
☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 0

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Photos

Others

TOTAL

Rep. Formel: PRS 7p

Lump Sum / L.B. / L.C. 4400

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/07/2020 12:55
Date Of Accident	01/07/2020 14:00
Exact Location Of Accident	ANG MO KIO AVENUE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBQ8395U
Insured/Policyholder	
Name Of Registered Owner	PYRO LEASING PTE. LTD.
Co Reg No	2XXXXX120G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-85000420

Vehicle Particulars

Manufacturer	HONDA
Model	CB190X MANUAL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5116807932-000097 COMP
Cover Note Number	

Driver

Name of Driver	DYLAN JAMES SCULLY
NRIC No	SXXXX368F
Date Of Birth	03/09/1994
Occupation	OUTDOOR
Date Of Driving Pass	15/03/2018
Driving Experience	2 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87799394
Fax Number	
Contact Number	
Email Address	SCULLY.DYLAN.JAMES@OUTLOOK.COM

Address	BLK 722 TAMPINES STREET 72 #15-17
Postcode	520722
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK POLICE DIVISIONAL HQ (G DIVISION)
Police Station Address	ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2440000 - FAX NO: 64443009
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE943D
Vehicle Make/Model/Colour	TOYOTA DYNA 150 MANUAL
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	DYLAN JAMES SCULLY
Approximate Age	25
Injuries Sustain	
Injured person in which vehicle?	FBQ8395U
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


- 3 JUL 2020

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vacom.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was riding on in my lane when BGE 943D cut into my lane without signal colliding with me.

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

- 3 JUL 2020

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:



SINGAPORE POLICE FORCE



T/20200706/7020

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20200706/7020

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/07/2020 23:25		Vide Report No.: G/20200702/7036		Station Diary No.:	
Informant's Particulars					
Name of Informant: DYLAN JAMES SCULLY			Address: APT BLK 722 TAMPINES STREET 72 #15-17 SINGAPORE 520722		
ID Type / ID No.: NRIC NO / S9431368F			Contact No.: Home/Office:		Mobile: 87799394
Nationality: SINGAPORE CITIZEN			Email: scully.dylan.james@outlook.com		
Sex: Male	Age: 25	Date of Birth: 03/09/1994	Type of Informant: Rider		
Race: Eurasian			Language: English		Institution / School Name:
Occupation: F&B MANAGER			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 01/07/2020 14:00	Type of Location: Straight Road
Location: ANG MO KIO AVENUE 1				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBQ8395U	Motorcycle					0
GBE943D	Van			White		0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20200706/7020

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20200706/7020

CONTINUATION OF REPORT

Rider			
Name	DYLAN JAMES SCULLY	ID No.	S9431368F
Related Vehicle	FBQ8395U (Motorcycle)	Contact No.	87799394
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	01/07/2020	Date Discharge	01/07/2020
No. of Days granted Medical Leave	07	Degree of Injury	Serious
Driver			
Name	LI XIANG HUA	ID No.	NIL
Related Vehicle	GBE943D (Van)	Contact No.	83719286
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I was riding (FBG2086D) along AMK ave 1 towards AMK ave 10 in lane 3 when (GBE943D) suddenly cut into my lane from lane 2 without any signal or caution. I am on 7 days Hospitalisation leave.



**SINGAPORE
POLICE FORCE**



T/20200706/7020

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20200706/7020

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
06/07/2020 23:25

Classification Of Case:

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE 510607

BUSINESS REGN. No. 53193457L

Hp: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Ms Pyro Leasing Pte Ltd
c/o Goh JP & Wong Advocates & Solicitors
133 New Bridge Road # 16-09
Chinatown Point
Singapore 059413

Our Ref : PA/FBQ8395/0720/tpw
Date : 14 October 2020

REFERENCES

Claim Type	: Third Party	Date of Accident	: 01 July 2020
Vehicle No.	: FBQ 8395 U	Date of Assignment	: 23 July 2020
Make	: Honda	Date of Inspection	: 23 July 2020
Model	: CB190X Manual	Date of Re-inspection	: 02 October 2020
Reg. Date	: 24 December 2019	COE Expiry	: 23 December 2029
Color	: Red	Chassis No	: LWBPC1A1K1000431
Odometer	: 4,737 km	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Radial	110/70-17	5mm
Rear	Radial	140/70-17	6mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and left side.
Please refer to photographs and assessment of repairs for details
Enclosed (62) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$8,039.35 Revised Assessment \$6,400.00 Lump sum

Survey conducted at M1 Motoring (Changi)

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Seven (7) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock
Reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICES

Vehicle No: FBQ 8395 U

Our Ref : PA/FBQ8395/0720/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation
1	Windscreen set ✓	1 pc	Scratches	286.00	286.00
2	Handle bar	1 pc	Bent	140.00	140.00
3	Handle bar balancer	1 set	Cut	80.00	80.00
4	Handlebar holder upper	1 pc	Usable	153.80	~
5	Clutch lever	1 pc	Cut	36.00	36.00
6	Brake lever	1 pc	Bent	42.00	42.00
7	Mirror assy	1 set	Cut	160.00	160.00
8	Headlight cowling ✓	1 pc	Cut	380.00	380.00
9	Headlight cowling lower ✓	1 pc	Grazed	209.00	209.00
10	Headlight assy (LED) ✓	1 pc	Scratches	680.00	455 680.00
11	Front signal light assy (LED) @ \$125/- ✓	2 pcs	Grazed	250.00	250.00
12	Front fork assy @ \$480/- 280	2 pcs	Bent	960.00	560 960.00
13	Stern steering ✓	1 pc	Distorted	210.00	210.00
14	Front fender ✓	1 pc	Cracked	151.20	151.20
15	Fuel tank side cover (silver) @ \$240/- 200	2 pcs	Deformed/cut	480.00	400 480.00
16	Fuel tank top side cover (red) @ \$105/-	2 pcs	LH cracked	210.00	105.00 ✓
17	Front side shroud cowling set @ \$285/- 240	2 pcs	Cracked LH	570.00	240 285.00
18	Front footrest assy LH	1 pc	Bent	60.00	60.00
19	Footrest bracket LH	1 pc	Bent	95.00	95.00
20	Gear pedal	1 pc	Cut	48.00	48.00
21	Rear fairing LH	1 pc	Cut	120.50	120.50 R
				3906.50	4,777.70
List price less 10%				3515.85	477.77
				4,789.35	4,299.93

Special Nett Items

22	Steering cone & bearing	1 set	Necessary	160.00	160.00
23	Engine guard	1 set	Bent/cut	500.00	420.00 380
24	Fog lamp (LED) @ \$220/-	2 pcs	Cut	440.00	440.00 400
25	Front number plate	1 pc	Necessary	20.00	18.00
26	Handle bar guard	1 set	Cut	300.00	280.00 200
27	Rear box rack with base	1 set	Bent	280.00	250.00 x R
28	Rear box	1 pc	Cut	350.00	280.00 250
				2,050.00	1,848.00 1408

PRUDENT ADJUSTORS SERVICES


Vehicle No: FBQ 8395 U

Our Ref : PA/FBQ8395/0720/tpw

Labours

Transportation (2 trips)	150.00	120.00
Body chassis repair & alignment	550.00	450.00 200
Remove & renew damage parts	500.00	400.00 300
	1,200.00	970.00 620
Total parts & labours concluded	<u>8,039.35</u>	<u>7,117.93</u>
Lump sum repair adjustment (less 10% due to no used parts)		<u>6,400.00</u>

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services
Bok Jee Tan

3515.85
1408
620
5543.85
41584400
06 days

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 120G

Vehicle Details

Vehicle No.: FBQ8395U

Vehicle to be Exported: Yes

Intended Deregistration Date: 23 Jul 2020

Vehicle Make: HONDA

Vehicle Model: CB190X MANUAL

Primary Colour: Red

Manufacturing Year: 2019

Engine No.: WH161FMK19C00010

Chassis No.: LWPCL1A1K1000431

Maximum Power Output: -

Open Market Value: \$2,537.00

Original Registration Date: 24 Dec 2019

First Registration Date: 24 Dec 2019

Transfer Count: 2

Actual ARF Paid: \$381.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Dec 2029

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$3,658.00

COE Rebate Amount: \$2,926.00

Total Rebate Amount: \$2,926.00

The information contained herein is correct as at 23 Jul 2020

OK



(/listing/usedbike/gallery/honc

♡ 1 Likes

REPORT ERROR > (/LISTING/LISTING/ERROR/USEDBIKE/17272/)

SHARE (WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-CB190X-TOURISM/17272/)

Honda CB190X Tourism

Listing Type	Free Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB190X Tourism (/listing/usedbike/model/honda-cb190x-adventure/)
Engine Capacity	184cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	21/02/2019
COE Expiry Date	20/02/2029 (8 years 6 months left)
Mileage	7098km
No. of owners	1
Type of Vehicle	Sport Tourers (/listing/usedbike/model/motorcycle-for-sale/sport-tourers/)

Price: SGD\$13000

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.



ACCIDENT STATEMENT

Date Of Report 02/07/2020 16:28
Date Of Accident 01/07/2020 14:00
Exact Location Of Accident ANG MO KIO AVE 1 TOWARDS BISHAN
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE943D
Insured/Policyholder
Name Of Registered Owner FIRST OCEAN FOODS PTE LTD
Co Reg No 201408766M
Email Address SALES@FIRSTOCEAN.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-62828884

Vehicle Particulars

Manufacturer TOYOTA
Model DYNA 150 D-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken REPORTING ONLY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company LONPAC INSURANCE BHD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number Z/19/VC00/104411
Cover Note Number

Driver

Name of Driver LI XIANG HUA
Passport No/FIN G3921941M
Date Of Birth 23/12/1982
Occupation OUTDOOR
Date Of Driving Pass 22/09/2017
Driving Experience 2 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-83719286
Fax Number
Contact Number
Email Address NOEMAIL

Address	171 KAMPUNG AMPAT #01-03
Postcode	368330
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MACPHERSON NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 54 PIPIT ROAD #01-82/84 , POSTCODE: 370054 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7449999 - FAX NO: 65476366
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ATTACHED POLICE REPORT NO: T/20200702/2093.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBQ8395U
Vehicle Make/Model/Colour	
Details Of Properties	MOTORCYCLE
Vehicle Category	MOTORCYCLE
Name of Driver	SCULLY DYLAN JAMES
NRIC/Passport Number	
Contact Number	87799394
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBQ8395U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature *[Signature]*
(If driver is not the policyholder)
Date & Time: 5/10

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

POLICE REPORT-1 Pg. 1



SINGAPORE
POLICE FORCE



T/20200702/2093

1 of 3

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

Report No. T/20200702/2093

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/07/2020 20:41	Vide Report No.: E/20200701/0100	Station Diary No.: 95
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: LI XIANGHUA			Address: 59 LASIA AVENUE SINGAPORE 277866		
ID Type / ID No.: FIN NO / G3921941M			Contact No.: Home/Office: Mobile: 83719286		
Nationality: CHINESE			Email:		
Sex: Male	Age: 37	Date of Birth: 23/12/1982	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: DRIVER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 01/07/2020 14:00	Type of Location: Straight Road
Location: Along Road 1 ANG MO KIO AVENUE 1				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: NO COLLISION				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBQ8395U	Motorcycle				Slightly Damaged	0
GBE943D	Lorry				No Damage	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
GBE943D	LONPAC INSURANCE BHD.			



**SINGAPORE
POLICE FORCE**



T/20200702/2093

2 of 3

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

Report No: T/20200702/2093

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LI XIANGHUA	ID No.	G3921941M
Related Vehicle	NIL	Contact No.	83719286
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON 1/67/2020 AT ABOUT 1400HRS, I WAS TRAVELLING STRAIGHT ON THE 3RD OUT OF 4 LANES FROM THE RIGHT ALONG ANG MO KIO AVE 1. SUBSEQUENTLY, I MADE A LANE CHANGE FROM 3RD OUT OF 4 LANES TO 4TH OUT OF 4 LANES FROM THE RIGHT AS I WANTED TO MAKE A RIGHT TURN AT THE CORSS-JUNCTION AHEAD. I THEN SIGNALLED TO LEFT, CHECKED MY BLINDSPOT. I THEN MAKE THE LANE CHANGE AFTER I DEEMED THAT IT IS SAFE FOR ME TO MAKE THE LANE CHANGE.

AFTER I COMPLETELY MADE MY LANE CHANGE, I THEN LOOK AT MY SIDE MIRROR AND I SAW A BIKE(FBQ8395U) FALL OFF ONTO THE ROAD. I THEN STOPPED MY VEHICLE AND DECIDED TO HELP. SUDDENLY THE RIDER ACCUSED ME THAT IT IS MY FAULT THAT I HAVE CAUSED HIM THE FALL. HOWEVER THERE IS NO COLLISION BETWEEN MY VEHICLE AND THE SAID BIKE. TRAFFIC POLICE WAS THERE TO ASSIST WITH THE ACCIDENT. THE RIDER SUFFERED ABRASIONS HOWEVER DID NOT CONVEYED BY AMBULANCE. WE THEN MADE AN AGREEMENT FOR INSURANCE CLAIMS. HOWEVER, MY INSURANCE COMPANY ASKED ME TO MAKE A REPORT FOR RECORD PURPOSES.



SINGAPORE
POLICE FORCE



T/20200702/2093

3 of 3

Police Station Of Origin:
MacPherson NPP
54 Phipps Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

Report No. T/20200702/2093

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 MUHAMMAD ABDURRAHMAN
MUCARAK BIN ASMAWI

Signature Of Interpreter:
Not applicable


Officer In Charge Of Case:

 SINGAPORE
POLICE FORCE
Contact No.:

Authentication Stamp
NP158

SIGNATURE

Signature Of Informant:



Date/Time:
02/07/2020 20:41

Classification Of Case:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo





LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 19/20/20/VC00/023445

Your Ref : CS3/LPC20007697T1sf3e2

21 January 2021

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF FBQ8395

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of FBQ8395T
- b) GIA report FBQ8395T
- c) GIA report and photos of GBE943D

Kindly study the documents and let us have your report by 4 February 2021.

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192
SINGAPORE 510607
BUSINESS REGN. No. 53193457L
Hp: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Ms Pyro Leasing Pte Ltd
c/o Goh JP & Wong Advocates & Solicitors
133 New Bridge Road # 16-09
Chinatown Point
Singapore 059413

Our Ref : PA/FBQ8395/0720/tpw
Date : 14 October 2020

REFERENCES

Claim Type	: Third Party	Date of Accident	: 01 July 2020
Vehicle No.	: FBQ 8395 U	Date of Assignment	: 23 July 2020
Make	: Honda	Date of Inspection	: 23 July 2020
Model	: CB190X Manual	Date of Re-inspection	: 02 October 2020
Reg. Date	: 24 December 2019	COE Expiry	: 23 December 2029
Color	: Red	Chassis No	: LWBPC1A1K1000431
Odometer	: 4,737 km	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Radial	110/70-17	5mm
Rear	Radial	140/70-17	6mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and left side.
Please refer to photographs and assessment of repairs for details
Enclosed (62) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$8,039.35 Revised Assessment \$6,400.00 Lump sum

Survey conducted at M1 Motoring (Changi)

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Seven (7) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock
Reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICES

Vehicle No: FBQ 8395 U

Our Ref : PA/FBQ8395/0720/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation
1	Windscreen set	1 pc	Scratches	286.00	286.00
2	Handle bar	1 pc	Bent	140.00	140.00
3	Handle bar balancer	1 set	Cut	80.00	80.00
4	Handlebar holder upper	1 pc	Usable	153.80	~
5	Clutch lever	1 pc	Cut	36.00	36.00
6	Brake lever	1 pc	Bent	42.00	42.00
7	Mirror assy	1 set	Cut	160.00	160.00
8	Headlight cowling	1 pc	Cut	380.00	380.00
9	Headlight cowling lower	1 pc	Grazed	209.00	209.00
10	Headlight assy (LED)	1 pc	Scratches	680.00	680.00
11	Front signal light assy (LED) @ \$125/-	2 pcs	Grazed	250.00	250.00
12	Front fork assy @ \$480/-	2 pcs	Bent	960.00	960.00
13	Stem steering	1 pc	Distorted	210.00	210.00
14	Front fender	1 pc	Cracked	151.20	151.20
15	Fuel tank side cover (silver) @ \$240/-	2 pcs	Deformed/cut	480.00	480.00
16	Fuel tank top side cover (red) @ \$105/-	2 pcs	LH cracked	210.00	105.00
17	Front side shroud cowling set @ \$285/-	2 pcs	Cracked LH	570.00	285.00
18	Front footrest assy LH	1 pc	Bent	60.00	60.00
19	Footrest bracket LH	1 pc	Bent	95.00	95.00
20	Gear pedal	1 pc	Cut	48.00	48.00
21	Rear fairing LH	1 pc	Cut	120.50	120.50
				5,321.50	4,777.70
	List price less 10%			532.15	477.77
				4,789.35	4,299.93
<u>Special Nett Items</u>					
22	Steering cone & bearing	1 set	Necessary	160.00	160.00
23	Engine guard	1 set	Bent/cut	500.00	420.00
24	Fog lamp (LED) @ \$220/-	2 pcs	Cut	440.00	440.00
25	Front number plate	1 pc	Necessary	20.00	18.00
26	Handle bar guard	1 set	Cut	300.00	280.00
27	Rear box rack with base	1 set	Bent	280.00	250.00
28	Rear box	1 pc	Cut	350.00	280.00
				2,050.00	1,848.00

PRUDENT ADJUSTORS SERVICES


Vehicle No: FBQ 8395 U

Our Ref : PA/FBQ8395/0720/tpw

Labours

Transportation (2 trips)	150.00	120.00
Body chassis repair & alignment	550.00	450.00
Remove & renew damage parts	500.00	400.00
	<u>1,200.00</u>	<u>970.00</u>
Total parts & labours concluded	<u>8,039.35</u>	<u>7,117.93</u>
Lump sum repair adjustment (less 10% due to no used parts)		<u>6,400.00</u>

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services
Bok Jee Tan

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 120G

Vehicle Details

Vehicle No.: FBQ8395U

Vehicle to be Exported: Yes

Intended Deregistration Date: 23 Jul 2020

Vehicle Make: HONDA

Vehicle Model: CB190X MANUAL

Primary Colour: Red

Manufacturing Year: 2019

Engine No.: WH161FMK19C00010

Chassis No.: LWBPCL1A1K1000431

Maximum Power Output: -

Open Market Value: \$2,537.00

Original Registration Date: 24 Dec 2019

First Registration Date: 24 Dec 2019

Transfer Count: 2

Actual ARF Paid: \$381.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Dec 2029

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$3,658.00

COE Rebate Amount: \$2,926.00

Total Rebate Amount: \$2,926.00

The information contained herein is correct as at 23 Jul 2020

OK



(/listing/usedbike/gallery/honc

♡ 1 Likes

REPORT ERROR > (/LISTING/LISTING/ERROR/USEDBIKE/17272/)

Share

SHARE (WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-CB190X-TOURISM/17272/)

Honda CB190X Tourism

Listing Type	Free Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB190X Tourism (/listing/usedbike/model/honda-cb190x-adventure/)
Engine Capacity	184cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	21/02/2019
COE Expiry Date	20/02/2029 (8 years 6 months left)
Mileage	7098km
No. of owners	1
Type of Vehicle	Sport Tourers (/listing/usedbike/model/motorcycle-for-sale/sport-tourers/)

Price: SGD\$13000