



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC20007697/T1qf3e2-1	
			Date: 04/02/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 943D	Veh. Inspected	FBQ 8395U	
Policy No.	Z/19/VC00/104411	Coverage (\$)	0.00	
Claim No.	19/20/20/VC00/023445	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	01/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB190X	c.c	184	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	LWBPCL1A1K1000431	Colour	RED / GREY	
Odometer	4737 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/70 R17	CST	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R17	CST	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/07/2020	Inspection Date	27/07/2020	
Survey held at	M 1 MOTORING 411 CHANGI ROAD SINGAPORE 419860			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	