



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 23.10.2020
Emailed : 10.03.2021, 2.15pm
Date Survey : 01.02.2021

VEHICLE NO : S 1528 CD
MODEL : KIA SPORTAGE 2.0 A
WIP : 23347

Table with 2 columns: Item, Amount. Rows include Material (\$3,023.20), Labour (\$2,220.00), Sub-Total (\$5,243.20), Less Excess (\$600.00), Total (\$4,643.20), GST 7% (\$325.02), Grand Total (\$4,968.22), and Finalise By/Date (LOI / 10/03/2021).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[] SURVEYOR'S REPORT REQUIRED

[] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends + 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[] TP claim

[] Claim GIA / LTA fee

[] Claim Loss of [] Use / [] Rental

[] Claim Medical Fee / Others

[] Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 01/02/2021	Cust No/Name	/Angelika Gottfriede Maria Saake
	Reg No/Reg Date	S1528CD / 20/10/2016
	Date In/Mileage	01/02/2021/ 26002
	Chassis/Package	KNAPN81AMG713243E
	Engine No	G4NAGH879467
	Make/Model	KIA/SPORTAGE 2.0 A G416
	Colour/Trim	KCS SPARKLING SILVE/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	10/03/2021/ 12:20	BLK	260 / AiTing	23347

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE LH FRONT DOOR, LH REAR DOOR, REPAIR LH SIDE SILL MOULDING, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 880.00
E PNT98000 RESPRAY ON LH FRONT DOOR, LH REAR DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 700.00
E PNT88000 TRANSFER LH FRONT DOOR ATTACHMENTS TO NEW PANEL				✓ 120.00
E PNT88000 TRANSFER LH REAR DOOR ATTACHMENTS TO NEW PANEL				✓ 120.00
M SUNDRY APPLY SEALANT ON AFFECTED AREAS				✓ 80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 120.00
A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT				✓ 120.00
M SUNDRY SUNDRIES				✓ 20.00
S SPECIALISTJOB REPLACE LH REAR SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING				✓ 30.00
X EXC EXCESS				-600.00
X PANEL ASSY-REAR DOOR,LH	1.00	✓ 819.00	20.00	655.20
X PANEL ASSY-FRONT DOOR,LH	1.00	✓ 970.00	20.00	776.00
X GARNISH ASSY-QTR SIDE,LH	1.00	✓ 128.00	20.00	102.40
X COVER-RR BUMPER LWR	1.00	? 457.00	20.00	365.60
X WHEEL ASSY-ALUMINIUM	1.00	✓ 1105.00	20.00	884.00
X MOULDING ASSY-SIDE SILL,LH	1.00	✓ 265.00	20.00	212.00
X BLACK TAPE-FRT DR FRAME RR ORT → Supp	1.00	7.00	20.00	5.60

Pro Forma

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 01/02/2021	Cust No/Name	/Angelika Gottfriede Maria Saake
	Reg No/Reg Date	S1528CD / 20/10/2016
	Date In/Mileage	01/02/2021/ 26002
	Chassis/Package	KNAPN81AMG713243E
	Engine No	G4NAGH879467
	Make/Model	KIA/SPORTAGE 2.0 A G416
	Colour/Trim	KCS SPARKLING SILVE/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	10/03/2021/ 12:20	BLK	260 / AiTing	23347

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BLACK TAPE-RR DR FRAME FR OTR,	1.00	7.00	20.00	5.60
X FILM-RR DR ANTI CHIPPING,LH	1.00	21.00	20.00	16.80
Z TEXT AIG OD CLAIM DOA : 23.10.20 SURVEYOR STEVE LKK 01.02.21 POLICY NO: 2100486884-04				

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,023.20	Nett	4,643.20
Labour	2,090.00	7% GST on	325.02
Standard Menu	0.00		
Specialist Job	30.00	Total Payable	4,968.22
Diagnostics Job	0.00		
Sundry/Others	-500.00		
Total(w/o GST)	4,643.20		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: S 1528 CD

	<u>Materials</u>	<u>Cost (\$)</u>
1	Black tape-frt dr frame DD Ort	7.00 / <i>NEC</i>
2	Black tape-RR Dr frame Fr Otr	7.00 / <i>NEC</i>
3	Film-RR dr anti chipping, LH	21.00 / <i>NEC</i>

	Total	35.00
	Less 20% discount	7.00
	Total after discount	28.00
	7% GST	1.96

	Grand total	\$ <u>29.96</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

Fault Code Searching

Rescan Erase All DTC Go to DTC Save

BCM
 SJB
 CLU

11/11

System	Status	Result
EPS	No Current DTC	Good
TPMS	No Current DTC	Good
SMK	No Current DTC	Good
CLU	No Current DTC	Good
SJB	No Current DTC	Good
BCM	No Current DTC	Good

System	DTC	Description	State
AIRBAG	B174800	P-SIS(Side Impact Sensor, Pressure) Front-Passenger Communication Error(DO NOT	History

S/W Ver.	M-E-K-01-00-0238	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0179	OS Ver.	Android 10

Work Order: R001346
 License: s1528cd
 Technician: 810119 kfsan
 Mileage: 26002
 Date: 8.2.21 17:57

Kia : Sportage : 2016- (QL/QLE) : All Wheel Drive

Front : Left

Actual	Before	Specified Range
-0°27'	-0°26'	-1°00' 0°00'
4°30'	4°30'	4°06' 5°06'
0°03'	0°11'*	0°00' 0°06'
11°27'*	11°26'*	13°28' 14°28'
11°00'*	11°00'*	12°28' 14°28'

Front : Right

Actual	Before	Specified Range
-0°21'	-0°22'	-1°00' 0°00'
5°12'*	5°12'*	4°06' 5°06'
0°03'	-0°05'*	0°00' 0°06'
14°44'*	14°45'*	13°28' 14°28'
14°23'	14°23'	12°28' 14°28'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°06'	-0°04'	
-0°42'	-0°42'	
-3°17'	-3°19'	
0°06'	0°06'	0°00' 0°12'

Rear : Left

Actual	Before	Specified Range
-1°12'	-1°08'	-1°30' -0°30'
0°04'	-0°03'*	0°00' 0°12'

Rear : Right

Actual	Before	Specified Range
-1°28'	-1°34'*	-1°30' -0°30'
0°06'	0°04'	0°00' 0°12'

Camber
Toe

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°16'	0°26'	
0°10'	0°02'	0°00' 0°24'
-0°01'	-0°03'	

* This value is not within specification. Tire wear, handling and safety problems may result.