

COMFORTDELTA ENGINEERING PTE LTD
REPAIR ESTIMATE

Like

NTUC

Date: 01/02/2021
Time: 12:16:59
Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010043
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO: 105451349
REGN NO: SHC 1348F
MILEAGE: 000000000
MAKE: HYUNDAI
MODEL: IONIQ (G2)
DATE OF REGN: 11/09/2018
DATE/TIME IN: 10/01/2021 01:20
ACCIDENT DATE: 10/01/2021

JOB / PARTS DESCRIPTION

QTY IND UNIT PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1 L	459.40	20.00	367.52	/ DIS
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ MC
0003	04-01-0104-2288-G	BEAM-RR BUMPER	1 L	394.80	20.00	315.84	/ BT
0004	04-01-0104-3819-G	STAY-RR BUMPER LH	1 L	138.10	20.00	110.48	/ BT
0005	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00	/ P's
0006	04-01-0104-2544-G	CAP-RR HOOK	1 L	98.80	20.00	79.04	/ DIS
0007	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1.000 L	180.00	10.00	162.00	/ OM
0008	04-01-0104-2531-G	BRACKET ASSY-RR BUMPER SI	1 L	55.80	20.00	44.64	/ cut.
0009	04-01-0104-2370-G	LAMP ASSY-REAR FOG	1 L	201.50	20.00	161.20	✓ BR
0010	04-01-0104-2226-G	LAMP ASSY-LICENSE PLATE	1 L	85.30	20.00	68.24	✓ M's
0011	04-01-0104-0851-G	REFLECTOR/REFLEX ASSY-RR	1 L	41.45	20.00	33.16	✗ NN
0012	FNPS	NUMBER PLATE WITH TRIM CO	1 N	55.00	10.00	49.50	/ P's
0013	04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1 L	155.00	20.00	124.00	/ cut.

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 01.02.2021
Time: 12:16:59
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305451249
REGN NO : SHC1348E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 13.09.2018
DATE/TIME IN : 30.01.2021 01:2
ACCIDENT DATE : 30.01.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT	PRICE	DISC%	AMOUNT
0014 04-01-0104-2540-G COVER-RR BPR UNDER CTR	1	L		225.00	20.00	180.00
0015 04-01-0104-2546-G COVER-RR BUMPER SIDE UNDE	1	L		108.00	20.00	86.40
0016 09-01-0104-2184-G UNIT ASSY-BSD LH	1	L		1,625.00	20.00	1,300.00
SUB-TOTAL :						3,460.62
						2435.45

JOB NATURE

0000 23-01	TOWING FEE	60.00	X NN	-20%:	1948.36
0001 20-05	REAR FENDER ADVERTISMENT LOGO LH	100.00			235
0002 20-05	REAR FENDER ADVERTISMENT LOGO RH	100.00		-10%:	211.5
0003 L	PANEL BEATING	400.00	350		
0004 23-502	SPRAYPAINT ON AFFECTED AREA	300.00	250		
0005 17-01	CHECK ALL LIGHTING	50.00	30		

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.02.2021

Time: 12:16:59

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305451249
REGN NO : SHC1348E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 13.09.2018
DATE/TIME IN : 30.01.2021 01:2
ACCIDENT DATE : 30.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0006 20-22 REMOVE/REFIX REVERSE SENSOR
0007 L DIAGNOS & RESET BSD ASSY FAULT CODE

120.00 40

480.00 X NN

SUB-TOTAL : 1,610.00 870

TOTAL : 5,070.62 3029.86

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO -20%: 2400
SURVEYOR NAME & SIGNATURE
DATE :

2 X Days.

~~After 2 days~~ Complaints RepairsAfter ~~2 days~~ print photos.

Give Qs up

01/2/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: