



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21001467/QKvf3n2	
			Date: 24/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBG 3604H	Veh. Inspected	SLG 4139D
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2100317/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	01/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN X-TRAIL 2.0	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JN1JANT32Z0002539	Colour	WHITE
	Odometer	82228 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/65 R17	BRIDGESTONE	6 mm
	L/H Front Tyre	225/65 R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/65 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/65 R17	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/01/2021	Inspection Date	01/02/2021
	Survey held at	60 JALAN LAM HUAT, CARROS CENTRE #05-68		
	Repairer	MY CAR CONSULTANT PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	