

ASS. REC. BY:

REF: CS/SMO21001467/QKvf3

Special Instruction:

Surveyor: SUN PINASSIGNMENT (Office)From (Person): GRACE TEO of SMO Date/Time: 1/2/2021 1:01 PM

Estimated Cost: _____ Bill to: _____

OD ☒ IP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLG 4139D Insured: FBG 3604Hat Workshop m/s MY CAR CONSULTANT Tel: 88668832of 60 Jalan Lam Huat, Carros Centre #05-68Policy No: _____ Claim No: CMTD2100317/GPL

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28.01.21
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 1-21-21 1.114P.MPerson Contacted: HUI QINVehicle ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SLG 4139D - ☒
	FBG 3604H - ☒
2/2/21	Email preli revise to Pau Loong
22/3/21	Sun Pin confirmed LS \$3200 (Red 14,412.27,81%)