



Kaki Bukit Autohub,
2 Kaki Bukit Ave 2, #01-18
Singapore 417921
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

Our Ref: **SLM 3937 S**
Your ref: **SHA 3398 H**

01 February 2021

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01/02 AXA TOWER
SINGAPORE 068811
Attn: Motor Claims Department

BY EMAIL motor.survey@axa.com.sg ONLY

Dear Sir/Madam,

DATE OF ACCIDENT : 29 Jan 2021
NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS
PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We are instructed by **GRAB RENTALS PTE LTD** to notify you of a road traffic accident on **29 Jan 2021** at about **06:00 HOURS** along **UBI AVE 1** our client's vehicle **SLM 3937 S & SHA 3398 H** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,



.....
N-51 AUTOMOTIVE PTE LTD