ASS. REC. BY: Steve REP: AIG

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess: $600.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

SIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Sum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMJ S913B Yr Regn: 13/3/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Texi / Prime Mover / Truck / Trailer or

Make: Mitsubishi Outlander c.c 1998

Colour Red A/C: Insured / Std / NI / N

Sp.Reading 113584 T/Radio: Insured / Std / NI / N

Eng/No:

C/No: GF7W 0700677

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or B Toyo

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mr
U/Bal.	4 mm	U/Bal.	4 mr
D.O.A.	1/2/21	D.O.I.	1/2/21

Survey held at Cycle & Carriage

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear LH

The U/C / Chassis frame / Body Structure affected due to collisio

Date / Time	Action / Instruction
	MV - 99K
	Finalise at $1470.86 before excess and GST, 4days
	RED: 1200.59;44%

ate/Time, File Rcvd to?

: Proll. Report

: Final Report

ate/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: : Site Insp ($)

: Interview ($)

: Tech. Invs ($)

: Weekend ($)

Survey Fee:

Transportation: S + RS S

Photos

Others

TOTAL

Approved :

Insp Sign / I.D.I: Fe