

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305451534
Date : 01/02/21
Time of Fax : _____

Via Fax : Email
Your Insured : SMF529G
Date of Acc : 31/01/21

Attn: Motor Claims Department

AIG

* 8 pages

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH C2523J

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

→ ♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
♦ Juman Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} limke@cdge.com.sg
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305451534
 REGN NO : SHC2523J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 07.11.2019
 DATE/TIME IN : 01.02.2021 14:55
 ACCIDENT DATE : 31.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-0578-G	COVER-FR BUMPER#	1	430.90	20.00	344.72
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60
0003	04-01-0104-2971-G	BRACKET-FR BUMPER SIDE SU	1	35.00	20.00	28.00
0004	04-01-0104-3918-G	BRACKET-FR BUMPER SIDE RH	1	28.00	20.00	22.40
0005	04-01-0104-0633-G	MOULDING-FRONT BUMPER RH	1	186.90	20.00	149.52
0006	04-01-0104-2935-G	LAMP ASSY-HEAD RH#	1	1,993.65	20.00	1,594.92
0007	04-01-0104-0573-G	PANEL-FENDER RH#	1	588.80	20.00	471.04
0008	04-01-0104-3913-G	EMBLEM-BLUE DRIVE RH	1	26.60	20.00	21.28
0009	03-01-0104-2137-G	CAP ASSY-WHEEL HUB	1	346.40	20.00	277.12

SUB-TOTAL : 2,926.60

JOB NATURE

0000 L	PANEL BEATING (repair or view mirror Rh)	600.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	550.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.02.2021

Time: 18:11:08

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305451534
REGN NO : SHC2523J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 07.11.2019
DATE/TIME IN : 01.02.2021 14:5
ACCIDENT DATE : 31.01.2021

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 17-01	CHECK ALL LIGHTING	50.00				
0003 20-08	ADJUST FRONT WHEEL ALIGNMENT	80.00				
SUB-TOTAL :						1,280.00

TOTAL : 4,206.60

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :