

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.02.2021

Time: 18:11:08

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305451534
 REGN NO : SHC2523J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 07.11.2019
 DATE/TIME IN : 01.02.2021 14:55
 ACCIDENT DATE : 31.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-0578-G	COVER-FR BUMPER#	1	430.90	20.00	344.72	any ✓
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60	ng ✓
0003	04-01-0104-2971-G	BRACKET-FR BUMPER SIDE SU	1	35.00	20.00	28.00	?
0004	04-01-0104-3918-G	BRACKET-FR BUMPER SIDE RH	1	28.00	20.00	22.40	?
0005	04-01-0104-0633-G	MOULDING-FRONT BUMPER RH	1	186.90	20.00	149.52	Rx ✓
0006	04-01-0104-2935-G	LAMP ASSY-HEAD RH#	1	1,993.65	20.00	1,594.92	?
0007	04-01-0104-0573-G	PANEL-FENDER RH#	1	588.80	20.00	471.04	ht ✓
0008	04-01-0104-3913-G	EMBLEM-BLUE DRIVE RH	1	26.60	20.00	21.28	ng ✓
0009	03-01-0104-2137-G	CAP ASSY-WHEEL HUB	1	346.40	20.00	277.12	cut ✓

SUB-TOTAL : 2,926.60

JOB NATURE

0000	L	PANEL BEATING (repair or view mirror Rh)	600.00	525
0001	23-502	SPRAYPAINT ON AFFECTED AREA	550.00	500

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305451534
REGN NO : SHC2523J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 07.11.2019
DATE/TIME IN : 01.02.2021 14:5
ACCIDENT DATE : 31.01.2021

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 17-01	CHECK ALL LIGHTING	50.00		30		
0003 20-08	ADJUST FRONT WHEEL ALIGNMENT	80.00		✓		
SUB-TOTAL						: 1,280.00
TOTAL						: 4,206.60

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Taufhin 97495745 with the
'wp' 2/2/21 24pm
p/p Resurvey before paint
Taufhin c. l. h. a. m. b. o. n.
2-3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items, must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date/Time: 01.02.2021 17:26

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305451534

OWNER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(R)

(O)

(P)

OUNT CARD NO.

REGN NO.

SHC2523J

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN

01.02.2021 14:55

YR OF MANU

07.11.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU188079

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 31.01.2021

NATURE: 3P 31.01.2021

S/NO

LABOR CODE

DESCRIPTION



ICKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHC2523J

LKE

Vehicle No.:

SHC2523J

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard