

↩ Reply all ▾ 🗑 Delete 🚫 Junk 🚫 Block ⋮

aigencrypt PRE-REPAIR INSPECTION REQUEST – SCE2323T vs SLA4941K (OI) on D.O.A.: 26/01/2021

① You replied on Tue 2/2/2021 12:14 PM

SD

Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>



Tue 2/2/2021 11:52 AM

To: Admin A; assignments

Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassi

aigencrypt PRE-REPAIR INSPE...

260 KB

Hi,

Please refer to the enclosed request from **M/s Chia S Arul LLC**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

*Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.*

(Please be informed that OI GIA Report is not available as insured has yet to report the accident)

Thanks & Regards,

Divyashni Subramaniam

AIG

FNOL Adjuster I

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1012103

Divyashni.Subramaniam@aig.com | www.aig.sg

From: Jerone <jerone@chiaarul.com>

Sent: Tuesday, February 2, 2021 11:34 AM

To: Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Teo, Ericweihong <Ericweihong.Teo@aig.com>; wengkit@chiaarul.com

Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLA4941K AND SCE2323T ON 26/01/2021

This message is from an external sender; be cautious with links and attachments.