

ASS. REC. BY: Taylor

REF: 033 | MSH 21001583 | T19, f3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD  / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 1001404466

Claims No. 252359

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 91226

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WR1 PRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMR2305J Yr Regn: 2019, Dec.

Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make: Manuel Beniz GL4180 C.C 1595

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 15985 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WD C1569422 J677699

Gen. Cond:  Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental.

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm / R/Bal. 6 mm

L/Bal. 6 mm / L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 2/2/21

Survey held at Eco Automobile

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair Range: \$10K - \$12K, 7 days.</u>
	<u>Submit PRS.</u>

Date/Time, File Pass to?  : Prel. Report

04/02 Typist  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: MER-PRS

Lump Sum / L.B.L. (?) \_\_\_\_\_

Days Of Repair: 7

Resurvey No. of Trip: 1

- Add Fee:
- : Site Insp (\$ \_\_\_\_\_)
  - : Interview (\$ \_\_\_\_\_)
  - : Tech. Invs (\$ \_\_\_\_\_)
  - : Weekend (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____
S + RS	_____ \$
Photos	_____
Others	_____
TOTAL	_____