



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21001601/Kvf3q2 Date: 16/03/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMF 9897J	Veh. Inspected	SMN 440K	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10008896/JM	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	02/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VOXY (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	ZWR800386459	Colour	METALLIC BLACK	
Odometer	133776 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	9 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	9 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	9 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/01/2021	Inspection Date	03/02/2021	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	