

ASS. REC. BY:

REF: CS3/AIG21001623/Gtf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Divyashni Subramaniam of AIG Date/Time: 3/2/2021 9:37 AM

Estimated Cost: Bill to:

OD ☒ TP WS/ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 6204P Insured: SFT 8946S

at Workshop m/s Sin Hock Lee Motor Repair Tel: 9272 6000

of Blk 51 Ubi Avenue 1, #01-09 Paya Ubi Industrial Park

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 02/02/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 2-3-21 12.49P.M Person Contacted: LEONG Vehicle IN ☒ OUT

Date/Time	Action/Instruction (X) Estimate
	SMD 6204P - X
	SFT 8946S - CC3/LCR17006865/R1zb3q2 DOA :01/04/2017