

ASS. REC. BY:

REF:

CS/AAP21001625/Rivf3

787K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 888Sat Workshop m/s WEARNESof 48, LNH KEE RDInsured: AAP

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 563k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLW 888S Yr Regn: 2018 / FEBType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BENTLY FUJIN SAU VGS / S/R c.c. 3993Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 10237 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SCBEE53WTHC066059

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRIM / STD A/Rim orTyre Size: F: 275/352R21

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 03/01/2021D.O.I. 09/02/2021

Survey held at

WEARNES

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rooftop / N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Int - 286K

Date/Time, File Pass to?



Prelt. Report



Final Report

Date/Time, File Return to?

2) 5/3/21-Typist

Report Format: TP

Lump Sum / L.S. (\$) _____

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$ _____)



Interview (\$ _____)



Tech. Invs (\$ _____)



Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

SERVICE ESTIMATE

95077 - C00001
 Ms Wang Qiujiao
 16 Leonie Hill Road
 #24-02

SL: SERVICE SALES - PC

Singapore 239198

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : Ms Wang Qiujiao

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 29/01/2021
 WIP No. . : 63091
 Veh.In/Out:
 *Tel.No. . :
 Reg.No. . : SLW888S
 Reg.date . : 01/02/2018
 Mileage .. : 0
 Chassis No: SCBEE53W7HC066059

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPAIR ROOF PANEL, REAR @14w	0	4200.00	0		4,200.00	S 28w
LH DOOR, ETC							
800	TO PUTTY SPRAY PAINT ON REAR @12w	0	3600.00	0		3,600.00	S 24w
LH DOOR, ROOF PANEL, ETC							
280	TO CHECK WIRING INCLUDE	0	1750.00	0		1,750.00	S
RESETTING OF ALL ELECTRICAL							
MODULES							

Paul
Hp 90010068
5 days
09/02/2021 @ 1130
Resy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
 Date: _____
 Labour Total 9,550.00
 Parts Total 0.00
 Package Total 0.00

Gross Total. 9,550.00
 Net..... 9,550.00
 GST @ 7.0% 668.50
 Total..... 10,218.50
 Paid..... 0.00
 Please Pay.. 10,218.50

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	12/01/2021 18:17 (SGT)
Date of Accident	03/01/2021 16:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	New Futura, 16 Leonie Hill Road - CP B1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLW888S

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	WANG QIU JIAO
Passport No/FIN	[REDACTED]
Email Address	[REDACTED]
Mobile Phone No	(Phone) +65-93969966
Alternative Phone No	+65-93969966

VEHICLE PARTICULARS

Manufacturer	Bentley
Model	Flying spur
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SD20V00931
Cover Note Number	-

DRIVER

Name of Driver	CHEN QINGYUAN
Passport No/FIN	[REDACTED]
Date Of Birth	[REDACTED]
Occupation	Indoor

Driving Pass	28/10/2020
Experience	3 MONTHS
Number	Male
Phone Number	(Phone) [REDACTED]
Mail Address	-
Address	[REDACTED]
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	No
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

My vehicle was stationary parked at 16 LEONIE HILL ROAD B1 carpark when I returned to my vehicle I saw there was a ceiling pipe line burst and white liquid was dripping onto my car roof and car left passenger door area. No injuries involved.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

12 Jan 2021

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SAIFULLAH S/O SYED MASOOD
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



Vehicle A SLW 888 S


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 VERIFY BY AJAX MARS (ARC)
 REPORTING OFFICER
 MOHAMED SAIFULLAH S/O SYED MASOOD
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

ACCIDENT STATEMENT (2000 characters)

My vehicle was stationary parked at 16 LEONIE HILL ROAD B1 carpark when I returned to my vehicle I saw there was a ceiling pipe line burst and white liquid was dripping onto my car roof and car left passenger door area. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SAIFULLAH S/O SYED MASOOD

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

12 January 2021 at 2:00 PM

Date/Time:

12 January 2021 at 2:00 PM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Foreign Identification Number
Owner ID:	787K

Vehicle No.:	SLW888S
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Feb 2021
Vehicle Make:	BENTLEY
Vehicle Model:	FLYING SPUR V8 SS/R
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CYC018563
Chassis No.:	SCBEE53W7HC066059
Maximum Power Output:	388.0 kW (520 bhp)
Open Market Value:	\$196,625.00
Original Registration Date:	01 Feb 2018
First Registration Date:	01 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$325,925.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Jan 2028
PARF Rebate Amount:	\$244,443.00

Intended COE Rebate Details

COE Expiry Date:	31 Jan 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$47,390.00
COE Rebate Amount:	\$31,580.00
Total Rebate Amount:	\$276,023.00

The information contained herein is correct as at 10 Feb 2021

OK

Blue

rt.com/used_cars/info.php?ID=967032&DL=2011

Bentley Flying Spur 4.0A V8

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price \$558,800

Depreciation \$57,390 /yr
View models with similar depre

Reg Date 01-Mar-2018
(7yrs 19days COE left)

Mileage 8,300 km (2.8k /yr)

Manufactured 2017

Road Tax \$3,940 /yr

Transmission Auto

Dereg Value \$261,019 as of today (change)

OMV \$186,605

COE \$44,000

ARF \$307,889

Engine Cap 3,993 cc

Power 373.0 kW (500 bhp)

Curb Weight 2,417 kg

No. of Owners 1

Type of Vehicle Luxury Sedan

Features

Powerful V8 Twin Turbocharged Engine Producing 500Bhp, 660 Nm Torque. 0-100Km In 4.8 Seconds, Top Speed: 303 Km/h. 8-Speed Auto Transmission, AWD. View specs of the Bentley Flying Spur (2013-2020)

