

Our Job Ref No : 305451533

Date : 21.02.21

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. : SHA6928J CTPL

01.02.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SLL2414X

2. The finalized amount shall be:

(a) Spare Parts after List discount \$0.00

(b) Labour Charges \$600.00

Total for Part-By-Part Repair Cost \$600.00

(c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and
finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Taufikh

Date : 23/2/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305451533
REGN NO : SHA6928J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 01.02.2021 14:10
ACCIDENT DATE : 01.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G COVER-FR BUMPER# 1 430.90 20.00 344.72 *Ry*
0002 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 22.00 20.00 17.60 *nn*

SUB-TOTAL : 362.32

JOB NATURE

0000 L PANEL BEATING 400.00 *350*
0001 23-502 SPRAYPAINT ON AFFECTED AREA 300.00 *250* 600

SUB-TOTAL : 700.00

TOTAL : 1,062.32

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

Tanphu 97445744
WP 02/2/21 E 4pm
02 days
P/P Reamy after upon
Tanphu C 1/1/2021

Wistake

\$600

2 days #

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305451533
REGN NO : SHA6928J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 01.02.2021 14:10
ACCIDENT DATE : 01.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 L PANEL BEATING 350.00

0001 23-502 SPRAYPAINT ON AFFECTED AREA 250.00

SUB-TOTAL : 600.00

TOTAL : 600.00

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO