

ASS. REC. BY:

Steve

REF:

A16

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

BIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Turn Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: _____

F: _____

R: _____

BS / DUN / EXNÖVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

Survey held at

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-7SK

Date/Time, File, Pass to?



: Prel. Report



: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Inve (\$ _____)



: West end (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$

Phone

Others

TOTAL

Special Form:

Date/Time, File, Pass to?



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
SIM POH KOK BLK 832 HOUGANG CENTRAL #04-540 SINGAPORE 530832 Contact No 62880398	Cust No/Name LCV10160/SIM POH KOK Reg No/Reg Date SML9311B / 12/06/201 Date In/Mileage / 0 Chassis No KNAF1416MK5044410 Engine No G4FGKH737201 Make/Model KIA/CERATO 1.6 A L S116 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV10160	CRDVCH	02/02/2021/ 17:50		442 / CocoLu	28470

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW SIDE SILL RH, REAR DOOR RH, REPAIR FRT DOOR RH S SPECIALISTJOB WO:1244344 ACCIDENT TOWED FROM HOUGANG CTR 830A TO CNC PG Date 2/2/21(Tue); Time Start 10.22am, Time End 11.44am Normal Towing \$50; Add: Accident \$10 Total Cost \$60	400X3			1200 1600.00
E PNT88000 REMOVE & INSTALL REAR DOOR TRIMS AND GLASS				150.00
E PNT98000 SPRAY PAINT FOR REAR DOOR RH, SIDE SILL RH, FRT DOOR RH	350X3			1050.00
M SUNDRY APPLY SEALANT FOR REAR DOOR RH				40.00
E PNT88000 RENEW REAR BUMPER, REAR FENDER RH & LH, BOOTLID, REAR LAMP HOUSING RH&LH REAR END PANEL 1 (1pr)	8 X 400			3200 5200.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS				300.00
E PNT88000 REAR MOVE & INSTALL REAR FENDER RH & LH TRIMS, CAR PET AND SEATS				400.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN				240.00
M SUNDRY APPLY SEALANT FOR REAR WINDSCREEN				80.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR FENDER RH & LH, REAR LAMP HOUSING RH & LH,	6 X 350			2100 2450.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
SIM POH KOK BLK 832 HOUGANG CENTRAL #04-540 SINGAPORE 530832 Contact No 62880398	Cust No/Name LCV10160/SIM POH KOK Reg No/Reg Date SML9311B / 12/06/201 Date In/Mileage / 0 Chassis No KNAF1416MK5044410 Engine No G4FGKH737201 Make/Model KIA/CERATO 1.6 A L S116 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV10160	CRDVCH	02/02/2021/ 17:50		442 / CocoLu	28470			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
USING HI-SCAN PRO TEST							160.00	
M	SUNDRY							40.00
APPLY SEALANT FOR ACCIDENT REAR PORTION							50.00	
M	SUNDRY							20.00
C&C LOGO								
M	SUNDRY							
NUMBER PLATE WITH FRAME								
M	SUNDRY							
Sundry				1.00	1208.00	00.00	1208.00	
M	PANEL-SIDE SILL OUTRER,RH	DO		1.00	1349.00	00.00	1349.00	
M	PANEL ASSY-QUARTER OUTER,RH	DO		1.00	1349.00	00.00	1349.00	
M	PANEL ASSY-QUARTER OUTER,LH	DO		1.00	135.00	00.00	135.00	
M	PANEL ASSY-RR COMB LAMP HSG,RH	RR BT		1.00	139.00	00.00	139.00	
M	PANEL ASSY-RR COMB LAMP HSG,LH	RR BT		1.00	1377.00	00.00	1377.00	
M	PANEL ASSY-REAR DOOR,RH	DO		1.00	8.00	00.00	8.00	
M	BLACK TAPE-RR DR FRAME RR OTR,	nec		1.00	13.00	00.00	13.00	
M	BLACK TAPE-RR DR FR,RH	nec		1.00	1297.00	00.00	1297.00	
M	PANEL ASSY-TRUNK LID	DO		1.00	324.00	00.00	324.00	
M	PANEL ASSY-BACK	X R		1.00	97.00	00.00	97.00	
M	HINGE ASSY-TRUNK LID,RH	n		1.00	97.00	00.00	97.00	
M	HINGE ASSY-TRUNK LID,LH	n		1.00	32.00	00.00	32.00	
M	LOGO ASSY-KIA SUB	CUT		1.00	28.00	00.00	28.00	
M	EMBLEM-CERATO	nec		1.00	651.00	00.00	651.00	
M	COVER-RR BUMPER	BR		1.00	241.00	00.00	241.00	
M	COVER-RR BUMPER LWR	CUT		1.00	19.00	00.00	19.00	
M	COVER-RR BUMPER FOG LAMP,RH	CUT		1.00	19.00	00.00	19.00	
M	COVER-RR BUMPER FOG LAMP,LH	X		1.00	181.00	00.00	181.00	
M	LAMP ASSY-SIDE T/SIGNAL,RH	CUT		1.00	181.00	00.00	181.00	
M	LAMP ASSY-SIDE T/SIGNAL,LH	X		1.00	9.00	00.00	9.00	
M	BRACKET-RR BEAM UPR MTG,RH	?		1.00	9.00	00.00	9.00	
M	BRACKET-RR BEAM UPR MTG,LH	?		1.00	6.00	00.00	6.00	
M	BRACKET-RR BEAM LWR,CTR	?		2.00	6.00	00.00	12.00	
P	BRACKET-RR BEAM LWR MTG	?						

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
SIM POH KOK	Cust No/Name LCV10160/SIM POH KOK
BLK 832 HOUGANG CENTRAL	Reg No/Reg Date SML9311B / 12/06/201
#04-540	Date In/Mileage / 0
SINGAPORE 530832	Chassis No KNAF1416MK5044410
Contact No 62880398	Engine No G4FGKH737201
	Make/Model KIA/CERATO 1.6 A L S116
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV10160	CRDVCH	02/02/2021/ 17:50		442 / CocoLu	28470

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BEAM-RR BUMPER	1.00	318.00	00.00	318.00
M STAY-RR BUMPER RH	1.00	65.00	00.00	65.00
M STAY-RR BUMPER LH	1.00	65.00	00.00	65.00
M BRACKET-ASSY RR BPR SIDE UPR,R	1.00	31.00	00.00	31.00
M BRACKET ASSY-RR BPR SIDE UPR,L	1.00	25.00	00.00	25.00
M TRIM ASSY-TRUNK LID	1.00	202.00	00.00	202.00
M W/STRIP-TRUNK LID OPNG	1.00	100.00	00.00	100.00
M LATCH ASSY-TRUNK LID	1.00	112.00	00.00	112.00
M STRIKER ASSY-TRUNK LID	1.00	40.00	00.00	40.00
M LAMP ASSY-REAR COMB INSIDE, RH	1.00	242.00	00.00	242.00
M LAMP ASSY-REAR COMB INSIDE, LH	1.00	242.00	00.00	242.00
M LAMP ASSY-REAR COMB OUTSIDE, RH	1.00	274.00	00.00	274.00
M LAMP ASSY-REAR COMB OUTSIDE, LH	1.00	274.00	00.00	274.00
M LAMP ASSY-CENTER GARNISH	1.00	638.00	00.00	638.00
M TRIM ASSY-RR TRANSVERSE	1.00	41.00	00.00	41.00
M TRIM ASSY-LUGGAGE SIDE RH	1.00	200.00	00.00	200.00
M TRIM ASSY-LUGGAGE SIDE LH	1.00	200.00	00.00	200.00
M MAT ASSY-LUGGAGE COVERING	1.00	211.00	00.00	211.00

Steve CLKK)

3/2/21, 11.00am

00- AM AL

EXPRS - ?

PIP

By BL SM

20 days

Date: _____

Signature: _____

Acknowledged by Repairer

is subject to final approval from Insurance Company

• Supplementary item(s) must be reserved and

• No illegal modification(s) is allowed

• Third party survey is on a "Without Prejudice" basis

• Parts prices are subject to confirmation

• To display damaged part(s) during survey

• To reserve before repair work commencing

Confirm & accepted by the Repairer of the vehicle

LKK Auto Consultants hence notified

Nett 24,051.00
 7% GST on 24051.00 1683.57
Total Payable 25,734.57

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/02/2021 12:02 (SGT)
Date of Accident	02/02/2021 02:53 (SGT)
Exact Location of Accident	805 Hougang Central, Singapore 530805
Additional Location Information	830A MULTI-STOREY CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML9311B
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	SIM POH KOK
NRIC No	SXXXX265A
Email Address	PKSIM2004@GMAIL.COM
Mobile Phone No	(Phone) +65-96452296
Alternative Phone No	+65-96452296

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900105468
Cover Note Number	-

DRIVER

Name of Driver	SIM YOCK SENG
NRIC No	SXXXX682I
Date Of Birth	28/06/1996
Occupation	Indoor

Date Of Driving Pass	20/11/2020
Driving experience	3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-84280584
Alt. Phone Number	-
Email Address	PKSIM2004@GMAIL.COM
Address	BLK 832 HOUGANG CENTRAL #04-540
Address complement	-
Postcode	530832
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	No
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	MR SIM
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

2/2/2021 11:42

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was parked at a lot and I chafed my mind because it was too greasy. I wanted to ~~reverse~~^{drive} out and I scraped the side of the car. I panicked and I reversed the car back and ~~at~~ I wanted to step on the brake pedal, I misjudged and stepped on the accelerator pedal instead. The car accelerated backwards and the car fell into the metal railings. The car bounced back up and I ~~called~~^{called} pulled the hand brake and called my dad immediately.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time

2/2/21 11:42.



Witnessed by Reporting Centre Personnel



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Sim Poh Kok
Period of Insurance : 12 Jun 2019 To 11 Jun 2021
Engine No. : G4FGKH737201
Chassis No. : KNAF1416MK5044410

Vehicle No. : SML9311B
Policy No. : 1900105468
Endorsement No. :
Issued Date : 17 Jun 2019

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2019
Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Sim Poh Kok - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2 Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

3 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504624203

FULCOKICP2 - FW

22 UBI ROAD 4 FULCO BUILDING

SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manik

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCNM