

ASS. No. BY:

PRC

CS3/ Lpc 21001632/Gvf3

ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

NEO Auto

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$49K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

X

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLF5098 L

29 Aug 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda

2.1.5

C.C 1496

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

253 155

T/Radio: Insured / Std / NI / NA

Eng/No:

MM6DL 2SAA GW209201

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A. 30/1/21

D.O.I.

03-02-21

Survey held at

w/s

4248 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

CCE: 37057

\$3000 - \$4000

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 5

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

4/2/21-Typist

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp. (\$

☐

Workshop (\$

Survey Fee:

Transportation

34 RS

Photos

Notes

Page 1

PRS