

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Feb 2021)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC3314P/03/02/2021 08:19

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR WHEEL CAP LH	25.00	0.00	177.70
2	1		*REAR DOOR APPS STICKERS LH	0.00	0.00	*80.00 F
Sub Total (S\$)						426.40
- List Item Discount on L Items (S\$)						86.60
Total Parts (S\$)						339.80

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHC3314P/03/02/2021 08:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

177.70
25% - 133.27

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 OD/TP Case (Insurer)

Amount

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Labour Items

Lab.Type

Amount

- 1 PANEL BEATING - REAR FENDER LH ETC
- 2 SPRAY PAINTING - ROCKER PANEL GARNISH LH ETC
- 3 TUFF KOTE

New

400.00

350

New

900.00

625

New

60.00

211

Gross Labour Cost (S\$)

1,360.00

ComfortDelGro Engineering Pte Ltd/SHC3314P/03/02/2021 08:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97443749
WP' 3/2/2024pm
1/p Resurvey after repair
Tanpin @ 1/1/2024
2 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: