

ASS. REC. BY: Taylor

REF: CS/CT/21001642/712ds

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMA 5147T
 at Workshop m/s AP AUTOMOTIVE SERVICES
 of _____
 Insured: SJK 2456D
 Policy No. DMPCSNW00139532005
 Claims No. SNM21D200571C02
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMA 5147T Yr Regn: 2018, June
 Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Vezel C.C. 1496
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 4744 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RM/1233065
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/55R17
 R: 77
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 972K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS WP
 Date: _____ Person Contacted: John Vehicle: IN / OUT

Front 6 mm R/Bal. 6 mm
 L/Bal. 6 mm Rear 6 mm
 D.O.A. _____ D.O.I. 3/2/21
 Survey held at AP Auto
 Des. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
6/4/2021 @ 3.03PM	REVISED IA TO IRENE TAY VIA MERIMEN.
09/09/21	LS \$6150, 6 days. (Red \$14137.58, 70%)

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 10/09 Typist
 Date/Time, File Return to?

Days Of Repair: 6
 Resurvey No. of Trip: 1

2) _____
 Report Format: MER-TP
 Lump Sum 6150

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
\$ + RS. SI	_____
Photo:	_____
Others:	_____
TOTAL	_____

Estimation

Date
Vehicle SMA 5147 T
Make/Model HONDA VEZEL
Chassis No.

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	HEADLAMP RH	1	\$ 1,796.50	\$ <i>cur</i> 1,796.50
2	HEADLAMP BRACKET RH	1	\$ 50.70	\$ <i>cur</i> 50.70
3	FRONT BUMPER	1	\$ 815.60	\$ <i>de</i> 815.60
4	FRONT BUMPER RETAINER RH	1		\$ <i>de</i> -
5	FRONT BUMPER SPONGE	1		\$ X -
6	FRONT FENDER RH	1	\$ 379.75	\$ <i>bk</i> 379.75
7	FRONT FENDER COWLING RH	1	\$ 150.90	\$ <i>fu</i> 150.90
8	FRONT WHEEL ARC PROTECTOR RH	1	\$ 187.50	\$ <i>art</i> 187.50
9	FRONT DOOR RH	1	\$ 1,208.55	\$ <i>bk</i> 1,208.55
10	FRONT DOOR SIDE MIRROR ASSY RH	1		\$ X -
11	FRONT DOOR SIDE MIRROR COVER RH	1		\$ X -
12	FRONT DOOR WINDOW MOULDING RH	1	\$ 245.65	\$ X 245.65
13	FRONT DOOR INNER WINDOW MOULDING RH	1	\$ 245.65	\$ X 245.65
14	FRONT DOOR WINDOW STICKER RH <i>buk</i>	1	\$ 98.78	\$ <i>cur</i> 98.78
15	FRONT DOOR HANDLE RH	1		\$ X -
16	FRONT DOOR LOCK RH	1	\$ 312.80	\$ X 312.80
17	FRONT DOOR LOCK CATCH RH	1	\$ 82.50	\$ X 82.50
18	FRONT DOOR INNER BOARD RH	1	\$ 727.50	\$ X 727.50
19	FRONT DOOR INNER BOARD SPEAKER RH	1		\$ X -
20	FRONT DOOR POWER WINDOW MOTOR RH	1		\$ X -
21	FRONT DOOR WINDOW REGULATOR RH	1	\$ 456.90	\$ X 456.90
22	FRONT DOOR HINGE UPPER & LOWER RH	2	\$ 114.95	\$? 229.90
23	FRONT DOOR CHECKER RH	1	\$ 150.70	\$ X 150.70
24	FRONT DOOR WEATHERSTRIP RH	1	\$ 233.15	\$? 233.15
25	FRONT DOOR INNER WEATHERSTRIP	1	\$ 179.40	\$ X 179.40
26	FRONT DOOR STEP GARNISH RH	1	\$ 291.70	\$ X 291.70
27	REAR DOOR RH	1	\$ 897.55	\$ <i>Ry</i> 897.55
28	REAR DOOR WEATHERSTRIP RH	3	\$ 60.65	\$ X 181.95
29	REAR DOOR INNER WEATHERSTRIP	1	\$ 107.85	\$ X 107.85
30	FRONT FENDER COWLING RH	1	\$ 150.90	\$ X 150.90
31	REAR WHEEL ARC PROTECTOR RH	1	\$ 187.50	\$ <i>art</i> 187.50
32	ROCKER PANEL RH	1	\$ 302.10	\$ <i>Ry</i> 302.10
33	REAR WHEEL ARC PROTECTOR RH	1	\$ 187.50	\$ <i>art</i> 187.50
34	FRONT ABSORBER RH	1		\$ X -
35	FRONT LOWER ARM RH	1		\$ X -
36	FRONT KNUCKLE RH	1		\$? -
37	FRONT KNUCKLE BEARING RH	1		\$? -

9859.48

38	FRONT BEARING HUB RH	1		\$ X	-
39	FRONT DRIVE SHAFT RH	1		\$ X	-
40	FRONT TIE ROD RH	1		\$ X	-
41	FRONT TIE ROD END RH	1		\$ X	-
42	FRONT RIM RH	1		\$ out - 800	800.350
43	REAR ABSORBER RH	1		\$ X	-
44	REAR LOWER ARM RH	1		\$ X	-
45	REAR KNUCKLE RH	1		\$ X	-
46	REAR KUNCKLE BEARING RH	1		\$ X	-
47	REAR BEARING HUB RH	1		\$ X	-
48	REAR RIM RH	1		\$ out - 500	500.350
				Total	\$ 4,171.48 10859.48
				Less 20%	\$ 834.30
				Total	\$ 3,337.18 8687.58

S/Nett Items					
1	FRONT BUMPER CLIPS	1	100	\$ 300 net	100.00
2	FRONT FENDER COWLING CLIPS	1	100	\$ 100 net	100.00
3	FRONT DOOR REFLECTIVE STICKER STRIP TOP	1	200	\$ 7	200.00
4	FRONT DOOR REFLECTIVE STICKER STRIP CENTER	1	200	\$	200.00
5	FRONT DOOR REFLECTIVE STICKER STRIP BOTTOM	1	200	\$	200.00
6	REAR DOOR REFLECTIVE STICKER STRIP TOP	1	200	\$	200.00
7	REAR DOOR REFLECTIVE STICKER STRIP CENTER	1	200	\$ 200	200.00
8	REAR DOOR REFLECTIVE STICKER STRIP BOTTOM	1	200	\$	200.00
9	ROCKER PANEL SEALANT	1	200	\$ X	200.00
10	ROCKER PANEL STEP GARNISH RH	1	2500	\$ 800 de	2,500.00
11	FRONT WHEEL ARC PROTECTOR CLIPS	1	100	\$ 100 net	100.00
12	REAR WHEEL ARC PROTECTOR CLIPS	1	100	\$ 100 net	100.00
13	FRONT TYRE RH	1	800	\$ X	800.00
14	REAR TYRE RH	1	800	\$ X	800.00
				Total	\$ 5,900.00

LABOUR					
1	SPRAY PAINT ON AFFECTED AREAS	1	1200	\$ 800	1,200.00
2	PANEL BEATING ON AFFECTED AREAS	1	1000	\$ 700	1,000.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	150	\$ 20	150.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	1	150	\$ X	150.00
5	TO RNR FRONT DOOR SIDE MIRROR	1	250	\$ X	250.00
6	TO RNR INNER TRIM AND UPHOISTERY	1	400	\$ X	400.00
7	TO CHECK WHEEL ALIGNMENT AND ADJUST	1	250	\$ 80	250.00
8	TO RNR UNDERCARRIAGE	1	250	\$ 120 ? plus	250.00
9	TO CHECK WHEEL BALANCING	1	250	\$ 30	250.00
10	TO PERFORM RUST PROOFING	1	400	\$ 40	400.00
11	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	600	\$ X	600.00
12	TO RNR FRONT AND DOOR MECHANISM	1	600	\$ 60	600.00

		Total Labour	\$ 5,500.00
		Parts Replacement Amount	\$ 9,237.18
		Total Amount	\$ 14,737.18 20087.58

Tamplin 9749544
 WP 3/2/21 @ 515 pm
 L/S resurvey after repair.
 6 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/02/2021 17:39 (SGT)
Date of Accident	29/01/2021 12:45 (SGT)
Exact Location of Accident	Gambas Ave, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA5147T
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	MOHAMMAD YAZID BIN MORSIDI
NRIC No	SXXXX452D
Email Address	e_zid@yahoo.com
Mobile Phone No	(Phone) +65-93288597
Alternative Phone No	+65-93288597

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Vezel
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5101305225-02
Cover Note Number	-

DRIVER

Name of Driver	MOHAMMAD YAZID BIN MORSIDI
NRIC No	SXXXX452D
Date Of Birth	04/09/1970
Occupation	Indoor

Date Of Driving Pass	13/05/1998
Driving experience	22 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93288597
Alt. Phone Number	+65-93288597
Email Address	e_zid@yahoo.com
Address	BLK 294 TAMPINES STREET 22
Address complement	#04-586
Postcode	520294
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLS REFER TO THE POLICE REPORT:T/20210129/7016

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK2456D
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	MOHAMMAD YAZID BIN MORSIDI
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	NECK & BODY
Injured person in which vehicle?	SMA5147T
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


 Policyholder's Signature / Date & Time


 Driver's Signature (if driver is not the policyholder) / Date & Time

 01/02/21
 Witnessed by Reporting Centre Personnel

Sketch Plan

