

ACC. REC. BY:

Steve

REF:

CS/A1621001651/EQ03

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 1900017477

Claims No. 4079072459SG


Sum Insured: Excess: 0/-

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Sum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SMJ 6305A

Yr Regn:

14/3/19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Attrage

c.c

1193

Colour:

Silver

A/C: Insured / Std / NI / N

Sp. Reading

28653

T/Radio: Insured / Std / NI / N

Eng/No:

MM B5TA13AKH 001292

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R15

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

3/2/21

D.O.I.

3/2/21

Survey held at

Cycle & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MIV-54K

04/02/21@5.31pm revert to AIG via Merimen.

04/02/21@6.02pm Kok Chong informed C/A via Merimen

05/02/21@8.15am Informed C&C C/A & ex:\$0/- by email.

04/03/21@5.54pm Confirmed with Ms Loi final fig \$9,715.02, 9 repair days. (Red \$3798.93, 28%)

Date/Time, File Pass to?



: Prell. Report

g)



: Final Report

Date/Time, File Return to?

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Pop Form: MER-OD

Final Sum / LE: 9715.02



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10695/YUEN HO TIAN Reg No/Reg Date SMJ6305A / 14/03/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH001202 Engine No 3A92UHN8611 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	03/02/2021/ 15:54	QUD	247 / DonBong	62604		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR <sup>1</sup> BOOT LID, REAR SPOILER LIP, REAR <sup>1</sup> BUMPER, REAR BODY KITS CUT/WELD REAR FLOOR PANEL, REAR <sup>3</sup> END PANEL. REPAIR RH <sup>1</sup> REAR FENDER, REPAIR <sup>1</sup> LH REAR FENDER				5x 450			3150.00 2250
E PNT88000 REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK							(phs) 120.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST							60.00
E PNT88000 TO REMOVE AND INSTALL REAR BODY KITS AND REAR SPOILER LIP							160.00
E PNT98000 PAINT WORK SPRAY REAR FLOOR PANEL, REAR END PANEL, REAR BOOT LID, REAR SPOILER, REAR <sup>1</sup> BUMPER, REAR BODY KITS, RH REAR FENDER, LH <sup>1</sup> REAR FENDER AND AFFECTED PORTION				6x 350			3150.00 2100
M SUNDRY PERFORM RUST PREVENTION							40 120.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							30.00
M SUNDRY APPLY BODY SEALANT							120.00
M SUNDRY SUPPLY C&C LOGO							40.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY SUPPLY REAR PARKING SENSOR — mufanthe							220.00
M SUNDRY SUPPLY REAR NUMBER PLATE WITH FRAME							50.00
A 13900099 REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR WORK							? 450.00
M SUNDRY							20 50.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10695/YUEN HO TIAN Reg No/Reg Date SMJ6305A / 14/03/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH001202 Engine No 3A92UHN8611 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	03/02/2021/ 15:54	QUD	247 / DonBong	62604

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SUNDRIES	1.00	956.00	23.00	736.12
M FLOOR,RR	1.00	425.00	23.00	327.25
M PANEL,RR END	1.00	195.00	23.00	150.15
M BOARD,TRUNK ROOM FLOOR	1.00	66.00	23.00	50.82
M TRIM,RR END	1.00	96.00	23.00	73.92
M ANT,KEYLESS OPERATION,RR	1.00	91.00	23.00	70.07
M BUZZER,KEYLESS OPERATIO,RR	1.00	20.00	23.00	15.40
M STRIKER,TRUNK LID LATCH	1.00	20.00	23.00	15.40
M STRIKER,TRUNK LID LATCH	1.00	157.00	23.00	120.89
M WEATHERSTRIP,TRUNK LID	1.00	791.00	23.00	609.07
M PANEL,TRUNK LID	1.00	21.00	23.00	16.17
M MARK,ATTRAGE	1.00	336.00	23.00	258.72
M GARNISH,RR END PANEL	1.00	335.00	23.00	257.95
M LAMP ASSY,COMB,RR LH	1.00	335.00	23.00	257.95
M LAMP ASSY,COMB,RR RH	1.00	23.00	23.00	17.71
M REFLECTOR LH	1.00	23.00	23.00	17.71
M REFLECTOR RH	1.00	51.00	23.00	39.27
M LAMP ASSY,LICENSE PLATE	1.00	51.00	23.00	39.27
M LAMP ASSY,LICENSE PLATE	1.00	30.00	23.00	23.10
M DUCT,RR VENTILATOR	1.00	40.00	23.00	30.80
M COVER,RR VENTILATOR	3.00	3.00	23.00	6.93
M CLIP,GEARSHIFT CONTROL LIN	1.00	28.00	23.00	21.56
M BRACKET,RR BUMPER,LH	1.00	28.00	23.00	21.56
M BRACKET,RR BUMPER,RH	6.00	4.00	23.00	18.48
M CLIP,FR BUMPER	1.00	748.00	23.00	575.96
M FACE,RR BUMPER	1.00	1643.00	00.00	1643.00
M ATTRAGE BODYKITS				

SURVEYOR NAME:

Steve CLKK

SURVEYOR SIGNATURE:

3/2/21, 4.00pm

DATE:

00-NH AL

REMARKS:

EXCISE - ?

Confirm &amp; accepted by

P/P  
M B&L SM  
9 chys

7% GST on

Nett  
13255.23

Total Payable

13,255.23  
927.87

14,183.10

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	03/02/2021 15:38 (SGT)
Date of Accident	03/02/2021 11:05 (SGT)
Exact Location of Accident	Near 90 Lim Chu Kang Lane 6F, Singapore 718873
Additional Location Information	JUNCTION OF MACRITCHIE TOWARDS FARRER ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMJ6305A

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	YUEN HO TIAN
NRIC No	SXXXX084I
Email Address	HOYUTI@OUTLOOK.COM
Mobile Phone No	(Phone) +65-96723677
Alternative Phone No	+65-96723677

#### VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

#### INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900017477
Cover Note Number	-

#### DRIVER

Name of Driver	YUEN HO TIAN
NRIC No	SXXXX084I
Date Of Birth	25/08/1962
Occupation	Outdoor

Date Of Driving Pass	08/04/1980
Driving experience	40 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96723677
Alt. Phone Number	+65-96723677
Email Address	HOYUTI@OUTLOOK.COM
Address	BLK 102 BISHAN STREET 12 #14-284
Address complement	-
Postcode	570102
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ3131C
Vehicle Manufacturer	Audi
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Black
Vehicle Category	Private car
Name of Driver	AUPELA LIM
Contact Number	(Phone) +65-96215622
Address	-
Address complement	-
Postcode	-
Insurance Company Name	Sompo



Amount Of Damage  
Details of property damaged in accident  
Of Passenger (Including Driver)

-  
-  
-

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that :
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

UAD 3/2/21  
Policyholder's Signature / Date & Time

Yuan Ho Tian 3/2/21  
Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]  
Witnessed by Reporting Centre Personnel

Sketch Plan

B A



Describe Circumstances of the Accident

Travelling from Adam Road toward Finner Road via traffic  
junction at Muebachde. Traffic light was green & I turned  
left while my car was about to cross. I pressed my brake &  
stop & the next thing that happened was as  
car knocked the back of my car.

Declaration

We declare the foregoing particulars are true in every respect.

 26/2/21

Policyholder's Signature / Date &  
Time



Driver's Signature (If driver is not the policyholder) / Date  
& Time



Witnessed by Reporting Centre  
Personnel



# CERTIFICATE OF INSURANCE

## CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : YUEN HO TIAN  
 Period of Insurance : 14 Mar 2019 To 13 Mar 2021  
 Engine No. : 3A92UHN8611  
 Chassis No. : MMBSTA13AKH001202

Vehicle No. : SMJ6305A  
 Policy No. : 1900017477  
 Endorsement No. : 000000000286140  
 Issued Date : 20 Jun 2019

### ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT  
 Engine Capacity/Tonnage : 1,193.00 CC  
 Driver Restriction : NA  
 Person or Classes of Persons Entitled to Drive\* :  
 Sum Insured : Market Value  
 Off Peak Car : No  
 First Year of Registration : 2019  
 Insuring with COE/PARF : Yes

a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.  
 You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition  
 Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

Section 1  
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2  
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

YUEN HO TIAN - \$600 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
4. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504620200

C&CMICP2 - AGNESL  
 239 ALEXANDRA ROAD  
 SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*Mobile*  
**AIG Asia Pacific Insurance Pte. Ltd.**  
 AUTHORISED REPRESENTATIVE

SSCSIM