



Service Request Details

Claim
S1M031Z1

Reference
None 

Loss Date
February 1, 2021

Report Date
Feb 3, 2021 12:00:00 AM

Request Date
February 4, 2021

Due Date
February 4, 2022

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pre-Repair Survey

Actions

Next Step
Finish the work

Complete Work

More ▾

Vehicle Information

Make
TPVD

Model
Volvo

Service Address

, , ,

Primary Contact/Insured

BIN BUJANG ABDUL RAHMAN
BLK 305 BUKIT BATOK STREET 31, #11-87, 650305, Singapore

noemail@com.sg

Claim Handler

CHEN Xinyou

chen.xinyou@axa.com.sg
Additional Instructions

- 3
- Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME	 REPLY FROM TP.msg
TYPE	Letters and Correspondence
SUB-TYPE	Solicitor / Advocate
AUTHOR	KUMAR Shailendra

DATE UPLOADED Februarv 4. 2021

TYPE	Reports & Statement
------	---------------------

SUB-TYPE	GIA Report
----------	------------

AUTHOR	KUMAR Shailendra
--------	------------------

DATE UPLOADED	February 3, 2021
---------------	------------------

NAME	 PRI TP EMAIL.msg
------	--

TYPE	Legal
------	-------

SUB-TYPE	Others
----------	--------

AUTHOR	KUMAR Shailendra
--------	------------------

DATE UPLOADED	February 3, 2021
---------------	------------------

NAME	 SKC6639Y INS GIA.pdf
------	--

TYPE	Reports & Statement
------	---------------------

SUB-TYPE	GIA Report
----------	------------

AUTHOR	KUMAR Shailendra
--------	------------------

DATE UPLOADED	February 3, 2021
---------------	------------------
