

ASS. REC. BY:

REF: CS3/CTI21001674/Gvf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): TAN KAH LEONG of CTI Date/Time: 04 Feb 2021 10:29

Estimated Cost: Bill to:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD 7490C Insured: GBF 7136R

at Workshop m/s RS Automotive Workshop Tel: 67483032

of 3066 Ubi Road 1, #01-394/384, 408700 Ubi

Policy No: DMCVSNA00010132003 Claim No: SNM21D200651

Sum Insured: Excess:

Make of Veh: D.O.A. 01/02/2021  
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement:

Date/Time: 4-2-21 11.49P.M Person Contacted: RS Vehicle IN ☒ OUT

| Date/Time | Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate |
|-----------|---------------------------------------------------------------------|
|           | GBD 7490C- <input checked="" type="checkbox"/>                      |
|           | GBF 7136R- <input checked="" type="checkbox"/>                      |
| 9/2/21    | Submit PRS, repair range \$2,000-\$3000 (4 days)                    |
|           |                                                                     |
|           |                                                                     |