


ASS. REC. BY: Steve REF: AIG

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMK 5990Y Yr Regn: 17/4/19
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: KIA Cerato cc 1591
Colour: White A/C: Insured / Std / NI / N
Sp. Reading: 32162 T/Radio: Insured / Std / NI / N
Eng/No: _____
C/No: KNAP 3416 MK 5036779
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modl: NII / S/Rim / STD A/Rim or
Tyre Size: F: 205 / 55 R16
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or N Ferq
Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 4/2/21 D.O.I. 4/2/21
Survey held at Cycle & Carriage
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooflap or
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MV-74K</u>

File/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

File/Time, File Return to?
2/3/21-Typist

Formal: Merimen
Nett Sum / L.P. / C: \$9707.60

Days Of Repair: 9
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Inve (%) _____
☐ : Weekend (\$) _____

Survey Fee:
Transportation: _____
S + RS: \$ _____
Photos: _____
Others: _____
TOTAL: _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09375/CHIA SZE LEA, DESMOND (XIE ZHIL Reg No/Reg Date SMK5990Y / 17/04/201 Date In/Mileage / 32162 Chassis No KNAF3416MK5036779 Engine No G4FGJH720081 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	04/02/2021/ 13:26	QUD	247 / DonBong	28558		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2400.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT FENDER				4 X 400			1600
E PNT88000							100.00
REMOVE AND REPLACE RADIATOR AND A/C CONDENSER							80.00
M SUNDRY							
TOP UP A/CON GAS AND CHECK A/CON SYSTEM							2100.00
E PNT98000							1750
PAINT WORK SPRAY FRONT BONNET, FRONT BUMPER FACE, RH FRONT DOOR, RH FRONT FENDER, LH FRONT FENDER AND AFFECTED PORTION				5 X 350			1750
M SUNDRY							120.00
APPLY BODY SEALANT							30.00
A 54900099							120.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							120.00
M SUNDRY							50.00
PERFORM RUST PREVENTION							400.00
A 10028901							50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							20
M SUNDRY							50.00
SUPPLY FRONT NUMBER PLATE WITH FRAME							
M SUNDRY							
RE-APPLY ZERONA COATING (pronto solar agent)							
M SUNDRY							
SUNDRIES							
M CARRIER ASSY-FRONT END MODULE / OR					1.00	675.00 20.00	540.00
M BEAM COMPLETE-FR BUMPER					1.00	497.00 20.00	397.60
M BLOWER ASSY					1.00	656.00 20.00	524.80
M RADIATOR ASSY					1.00	646.00 20.00	516.80
M CONDENSER ASSY-COOLER					1.00	687.00 20.00	549.60
M GUARD-AIR, RH					1.00	28.00 20.00	22.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09375/CHIA SZE LEA, DESMOND (XIE ZHIL Reg No/Reg Date SMK5990Y / 17/04/201 Date In/Mileage / 32162 Chassis No KNAF3416MK5036779 Engine No G4FGJH720081 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	04/02/2021/ 13:26	QUD	247 / DonBong	28558
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M GUARD-AIR, LH	X	1.00	28.00	20.00	22.40
M COOLANT (4L)	?	1.00	26.00	23.00	20.02
M LAMP ASSY-HEAD, RH	GR	1.00	1219.00	20.00	975.20
M BRACKET-FR BUMPER UPR SIDE MTG	?	1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG	?	1.00	22.00	20.00	17.60
M STIFFNER-FR BPR LWR	X	1.00	114.00	20.00	91.20
M ABSORBER-FRONT BUMPER ENERGY	GR	1.00	84.00	20.00	67.20
M LAMP ASSY-SIDE REPEATER, RH	CUT	1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER, RH	?	1.00	14.00	20.00	11.20
M MOULDING-FRONT BUMPER, RH	(f, l, p) - CUT	1.00	36.00	20.00	28.80
M GARNISH-RADIATOR GRILLE	GR - CIP (CUT)	1.00	38.00	20.00	30.40
M CLIP	APC	10.00	1.00	20.00	8.00
M GRILLE ASSY-RADIATOR	GR	1.00	328.00	20.00	262.40
M COVER-FR BUMPER	GR	1.00	633.00	20.00	506.40
M CAP-FRONT HOOK	CUT	1.00	9.00	20.00	7.20
M GRILLE-FRONT BUMPER	CUT (lower grille)	1.00	262.00	20.00	209.60
M COVER-FR BUMPER FOG LAMP, RH	X	1.00	15.00	20.00	12.00
M ORNAMENT-KIA NO.115	APC	1.00	32.00	20.00	25.60
M HINGE ASSY-HOOD, RH	BT	1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD, LH	BT	1.00	43.00	20.00	34.40
M PANEL ASSY-HOOD	OD	1.00	1502.00	20.00	1201.60
M INSULATOR-FENDER RH	X	1.00	27.00	20.00	21.60
M PANEL-FENDER, RH	OD	1.00	430.00	20.00	344.00
M ROD ASSY-HOOD STAY	TN	1.00	35.00	20.00	28.00
M LATCH ASSY-HOOD	X	1.00	103.00	20.00	82.40

SURVEYOR NAME: Steve CLKK) 4/2/21, 2.30pm
 SURVEYOR SIGNATURE: OD-NY AL
 DATE: EXCESS - ?
 REMARKS: P/P

Confirm & accepted by

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

By P/L SMY
 9 days

Nett 12,294.82
 7% GST on 12294.82 860.64
 Total Payable 13,155.46

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/02/2021 13:18 (SGT)
Date of Accident	03/02/2021 18:10 (SGT)
Exact Location of Accident	SLE, Singapore
Additional Location Information	SLE, AFTER EXIT OF WOODLANDS AVE 12
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMK5990Y

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHIA SZE LEA, DESMOND
NRIC No	SXXXX441E
Email Address	CHIADES@GMAIL.COM
Mobile Phone No	(Phone) +65-90212356
Alternative Phone No	+65-90212356

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900083585
Cover Note Number	-

DRIVER

Name of Driver	CHIA SZE LEA, DESMOND
NRIC No	SXXXX441E
Date Of Birth	02/12/1979
Occupation	Indoor

Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

20/08/2003
17 YEARS AND 6 MONTHS
Male
(Phone) +65-90212356
+65-90212356
CHIADES@GMAIL.COM
BLK 267 BISHAN STREET 24 #06-166
-
570267
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
2
No
-
Yes
1
No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
No
No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name

SLN1819H
-
-
-
-
Private car
CHEONG HAI LIANG STEVEN
(Phone) +65-97687694
-
-
-
-

Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Chin H/ Feb/21
Policyholder's Signature / Date &
Time 10:50hrs

Driver's Signature (If driver is not the policyholder) / Date
& Time

[Signature]
Witnessed by Reporting Centre
Personnel

Sketch Plan

→ Towards Exit Woodlands Ave 12



Describe Circumstances of the Accident


Car in front suddenly stopped, brake light seems vague though, by the time I noticed, I was unable to brake/stop in time to avoid knocking the car in front.

Declaration

We declare the foregoing particulars are true in every respect.

 04/feb/2021
Policyholder's Signature / Date &
Time 10:50 hrs.

Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel

CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : CHIA SZE LEA, DESMOND (XIE ZHILI, DESMOND)
Period of Insurance : 17 Apr 2019 To 16 Apr 2021
Engine No. : G4FGJH720081
Chassis No. : KNAF3416MK5036779

Vehicle No. : SMK5990Y
Policy No. : 1900083585
Endorsement No. :
Issued Date : 24 Apr 2019

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2019
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

CHIA SZE LEA, DESMOND (XIE ZHILI, DESMOND) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
 2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
 4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622210

C&CKICP2 - JAMES
 239 ALEXANDRA ROAD
 SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

56GNMO