



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 04/02/21
LIK - STEVE

VEHICLE NO : SMK 5990Y

MODEL : KIA/CERATO 1.6 A EX

WIP : 28558

Material	:	\$	<u>5,877.60</u>
Labour	:	\$	<u>3,830.00</u>
Sub-Total	:	\$	<u>9,707.60</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>9,107.60</u>
GST 7%	:	\$	<u>637.53</u>
Grand Total	:	\$	<u>9,745.13</u>
Finalise By/Date : <u>LARRY ON 22/02/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 09 WORKING DAYS + 4 days (2 weekends)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 04/02/2021	Cust No/Name	LCV09375/CHIA SZE LEA, DESMOND (XIE ZHIL
	Reg No/Reg Date	SMK5990Y / 17/04/2019
	Date In/Mileage	04/02/2021/ 32162
	Chassis/Package	KNAF3416MK5036779 /KC17P
	Engine No	G4FGJH720081
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	22/02/2021/ 08:11	BLD	884 / Lauro Songcuan	28558		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1600.00
RENEW DAMAGED PART ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, REPAIR RH FRONT DOOR, LH FRONT FENDER							
E PNT88000							100.00
REMOVE AND REPLACE RADIATOR AND AIRCON CONDENSER							
E PNT98000							1750.00
SPRAY PAINT FRONT BONNET, FRONT BUMPER FACE, RH FRONT DOOR, RH FRONT FENDER, LH FRONT FENDER AND AFFECTED PORTIONS							
M SUNDRY							40.00
APPLY BODY SEALANT ON AFFECTED AREAS							
A 54900099							30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
M SUNDRY							40.00
PERFORM RUST PREVENTION ON AFFECTED PORTIONS							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
M SUNDRY							20.00
SUNDRIES							
S SPECIALISTJOB							50.00
SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)							
S SPECIALISTJOB							80.00
VACUUM & TOP UP AIRCON GAS (CERATO)							
X EXC							-600.00
INSURANCE EXCESS							
X CARRIER ASSY-FRONT END MODULE ✓				1.00	675.00	20.00	540.00
X RADIATOR ASSY ?				1.00	646.00	20.00	516.80
X CONDENSER ASSY-COOLER ?				1.00	687.00	20.00	549.60
X GUARD-AIR,RH ?				1.00	28.00	20.00	22.40
X LAMP ASSY-HEAD,RH ✓				1.00	1219.00	20.00	975.20
X ABSORBER-FRONT BUMPER ENERGY ✓				1.00	84.00	20.00	67.20
X LAMP ASSY-SIDE REPEATER,RH ✓				1.00	143.00	20.00	114.40
X MOULDING-FRONT BUMPER,RH ✓				1.00	36.00	20.00	28.80

This is not an official tax invoice.

This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09375/CHIA SZE LEA, DESMOND (XIE ZHIL Reg No/Reg Date SMK5990Y / 17/04/2019 Date In/Mileage 04/02/2021/ 32162 Chassis/Package KNAF3416MK5036779 /KC17P Engine No G4FGJH720081 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK
04/02/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/02/2021/ 08:11	BLD	884 / Lauro Songcuan	28558

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X GARNISH-RADIATOR GRILLE ✓	1.00	38.00	20.00	30.40 ✓
X CLIP ✓	10.00	1.00	20.00	8.00 ✓
X GRILLE ASSY-RADIATOR ✓	1.00	328.00	20.00	262.40 ✓
X COVER-FR BUMPER ✓	1.00	633.00	20.00	506.40 ✓
X CAP-FRONT HOOK ✓	1.00	9.00	20.00	7.20 ✓
X GRILLE-FRONT BUMPER ✓	1.00	262.00	20.00	209.60 ✓
X ORNAMENT-KIA NO.115 ✓	1.00	32.00	20.00	25.60 ✓
X HINGE ASSY-HOOD,RH ✓	1.00	43.00	20.00	34.40 ✓
X HINGE ASSY-HOOD,LH ✓	1.00	43.00	20.00	34.40 ✓
X PANEL ASSY-HOOD ✓	1.00	1502.00	20.00	1201.60 ✓
X PANEL-FENDER,RH ✓	1.00	430.00	20.00	344.00 ✓
X ROD ASSY-HOOD STAY X	1.00	35.00	20.00	28.00 ✓
X WIRING ASSY-FEM	1.00	143.00	20.00	114.40 X
HORN ASSY-LOW PITCH	1.00	74.00	20.00	59.20 X
COVER ASSY-COWL TOP	1.00	247.00	20.00	197.60 X

TEXT
 AIG - OD CLAIM
 DOA: 03.02.2021
 SURVEY: STEVE (LKK) 04.02.21
 09 DAYS

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,877.60	Nett	9,107.60
Labour	3,600.00	7% GST on	637.53
Standard Menu	0.00		
Specialist Job	130.00		
Diagnostics Job	0.00	Total Payable	9,745.13
Sundry/Others	-500.00		
Total(w/o GST)	9,107.60		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMK 5990 Y

	<u>Material</u>	<u>Cost \$</u>
1	Wiring Assy- FEM	143.00 / BR
2	Horn Assy- Low Pitch	74.00 / BR
3	Cover Assy- Cowl Top	247.00 / CUT
		<u>464.00</u>
	20% Discount	<u>92.80</u>
		<u>371.20</u>
	7% GST	<u>25.98</u>
	Total	<u>397.18</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMK 5990YWIP: 28558

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	A/C condenser	2 / SUPP		RT	97606 m6000
2	Radiator	2 / SUPP		RT	87991 25310 m6100
3	Horn	2 / SUPP		RR	96611 m6000
4	Horn harness wiring fan	2 / SUPP		RR	91846 M6020
5	Alward Air RH	2 / SUPP		RR	29134 m6000
6	Cover top cowl	2 / SUPP		CUT Steve 9/2/11	86150 m6900
7		2 / SUPP			
8		2 / SUPP			
9		2 / SUPP			
10		2 / SUPP			
11		2 / SUPP			
12		2 / SUPP			
13		2 / SUPP			
14		2 / SUPP			
15		2 / SUPP			
16		2 / SUPP			
17		2 / SUPP			
18		2 / SUPP			
19		2 / SUPP			
20		2 / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CBRATO 1.6 BXSURVEYOR: Steve & LK

HOME
 Online

CERATO/FORTE../2019/G 1.6 MPI..

VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

ICU
 CLU
 IBU-SMK

9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.	M-E-K-01-00-0239	VCI Ver.	02.50
ECU Ver.	M-E-K-01-00-0180	OS Ver.	Android 10

HOME
 Online

CERATO/FORTE../2019/G 1.6 MPI..

VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

EPS
 AIRBAG
 ABS/ESC

5/5

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0239	VCI Ver.	02.50
ECU Ver.	M-E-K-01-00-0180	OS Ver.	Android 10