



Service Request Details

Claim

S1M03584

Reference

CC4/ASM21001692/Dga3q2 

Loss Date

31 January 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

13 Mar 2021 9:48:33 AM

Request Date

6 August 2021

Due Date

Services

Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Incident Vehicle Registration #
VCT3242

Make
TPVD

Model

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

CDGE COMFORT FILE TRANSFER : S1M031X6

- Messages4
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

▼

Document SubType

▼

+ Upload Documents

Already Attached

NAME	LKK Inspection.pdf
SUBTYPE	Surveyor/ Assessor expense
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	8 March 2022
NAME	LKKAdjustment1a.pdf
TYPE	Forms / Claim Documents
SUBTYPE	Others
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	8 March 2022
NAME	TP ESTIMATE - MARKED.pdf
TYPE	Forms / Claim Documents
SUBTYPE	Estimate / Quotation
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	23 November 2021
NAME	LKK RESURVEY PHOTO-1.pdf
TYPE	Forms / Claim Documents
SUBTYPE	Others
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	23 November 2021
NAME	LKK RESURVEY PHOTO-2.pdf
TYPE	Forms / Claim Documents

DATE UPLOADED	23 November 2021
NAME	 LKK SURVEY PHOTO.pdf.pdf
TYPE	Forms / Claim Documents
SUBTYPE	Others
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	23 November 2021
NAME	 TP - IA.pdf.pdf
TYPE	Forms / Claim Documents
SUBTYPE	Assessment
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	23 November 2021