

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 28/8/2018 12:11:37 PM
Attachments:  tmp5ADE.TIF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



27 August 2018

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120
Fax : 6415 3727

Dear Sirs

**ACCIDENT BETWEEN VEHICLE NO. SKX 76 A AND VEHICLE NO. EE 71 J ON
02/06/2018 @ 1700 Hrs**

We are the appointed repair workshop of vehicle no. SKX 76 A

We understand that you are the insurer of vehicle no. EE 71 J

The owner of vehicle number SKX 76 A has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800
Mobile No. 9006 4184 / peijie@expresscar.com.sg. Ms Shirley

Yours faithfully





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18015690/T1z4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 28-08-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | |
|--------------|---------------|----------------|------------|
| Insured Veh. | EE 71J | Veh. Inspected | SKX 76A |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | CHIN LEE YING | Assign Date | 28/08/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------|--------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| |
|--|
| |
|--|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 02/06/2018 | Inspection Date | 29/08/2018 |
| Survey held at | APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800. | | |

5a. Remarks

| |
|--|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |
|--|

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 25/08/2018 11:05
Date Of Accident 23/08/2018 17:55
Exact Location Of Accident AYE(TUAS) AT PORTSDOWN ROAD EXIT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKX76A
Insured/Policyholder LIM CHEE WEE
Name Of Registered Owner S7623590B
NRIC No LCW078@YAHOO.COM.SG
Email Address (LOCAL) +65-96194055
Mobile Phone No Office-96194055
Alternative Phone No

Vehicle Particulars

Manufacturer MERCEDES-BENZ
Model GLC250

Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken

Vehicle Category THIRD PARTY

Insurance Company

Name of Insurance Company AVIVA LTD
Type Of Coverage COMPREHENSIVE

Fleet Policy NO
Policy Number 10844826
Cover Note Number

Driver

Name of Driver LIM CHEE WEE
NRIC No S7623590B
Date Of Birth 01/08/1976
Occupation INDOOR
Date Of Driving Pass 25/05/1995
Driving Experience 23 YEARS AND 2 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96194055
Fax Number
Contact Number OFFICE-96194055
EMail Address LCW076@YAHOO.COM.SG
Address NA
Postcode

Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
-
-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

CLEMENTI POLICE DIVISIONAL HQ (D DIVISION)

Police Station Address

ROAD, 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-7740000 - FAX NO: 67741705

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO: (D/2018024/7008) ON 23/08/2018 I WAS DRIVING MY VEHICLE SKX76A ALONG AYE TOWARDS CLEMENTI DIRECTION. AT ABOUT 5:55PM, A VEHICLE BEARING EE71J SWERVE IN TO MY LANE FROM THE ROAD DIVIDER. THE VEHICLE HIT ON TO THE LEFT SIDE OF MY CAR. I SOUNDED MY HORN TO ASK THE VEHICLE TO STOP, HOWEVER HE SPEED OFF WITHOUT STOPPING. AFTER THE ACCIDENT, MY CAR IS PULLING TO THE RIGHT AND THERE IS A KNOCKING SOUND. THE INCIDENT WAS RECORDED ON MY DASH CAM. I AM LODGING THIS REPORT TO ASK THE POLICE TO INVESTIGATE THE CASE AND ALSO FOR INSURANCE CLAIM PURPOSES.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WILL UPLOAD TO FILEZILA ONCE INSURED SEND

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

EE71J

Vehicle Make/Model/Colour

MERCEDES BENZ/A45

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN DRIVER

NRIC/Passport Number

Contact Number


Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



POLICE REPORT



**SINGAPORE
POLICE FORCE**

POLICE REPORT (NP299)

Police Station Of Origin
Clementi Police Divisional HQ
20 Clementi Avenue 5 SINGAPORE 129858
Tel No. 1800-7740000



1 of 2

Report No. D201808247008

| | | |
|--|--|---|
| Date/Time Report Made 24/08/2018 11:53 | Video Report No. | Station Diary No. |
| Name Of Informant LIM CHEE WEE | Address APT BLK 28 JALAN LEMPENG #12-06 SINGAPORE 128807 | |
| ID Type / ID No. NRIC NO / S7623590B | Contact No. Home/Office | Mobile: 98194055 |
| Nationality SINGAPORE CITIZEN | Email Address lck076@ytahoo.com.sg | |
| Occupation COMPANY DIRECTOR | Sex Male | Age 42 |
| Institution/School Name | Date of Birth 28/07/1976 | Race Chinese |
| Date/Time Of Incident 23/08/2018 17:55 - 23/08/2018 18:00 | Language English | Location Of Incident APT BLK 28 JALAN LEMPENG #12-06 SINGAPORE 128807 |

Brief details.

On 23/08/2018 I was driving my vehicle SKX76A along AYE towards Clementi direction. At about 5:55PM, a vehicle bearing EE71J swerve in to my lane from from the road divider. The vehicle hit onto the left side of my car. I sounded my horn to ask the vehicle to stop, however he speed off without stopping. After the accident, my car is pulling to the right and there is a knocking sound. The incident was recorded on my dash cam. I am lodging this report to ask the police to investigate the race and also for

Insurance claim purposes.

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

24/08/2018 11:53

Classification Of Case:

POLICE REPORT



**SINGAPORE
POLICE FORCE**

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. D2018UB247008



1120740047008

2 of 2

Subjects Involved

Victim

| | | | |
|----------------|--------------------------|--------------|-----------|
| Person Name | LIM CHEE WEE | ID No | 57623560B |
| ID Type | NRIC NO | Age | 42 |
| Gender | Male | Language | English |
| Race | Chinese | Address Type | |
| Occupation | COMPANY DIRECTOR | Mobile No | 96194055 |
| Address | APT BLK 2b JALAN LEMPENG | | |
| | #12-06 SINGAPORE 128807 | | |
| Is Informant A | Yes | | |
| Victim? | | | |
| Person Name | LIM CHEE WEE (Informant) | | |

Signature Of Officer Recording The Report.

Not applicable

Signature Of Interpreter.

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant.
The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:
24/08/2018 11:53

Classification Of Case:

Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



01-18-2018
10:00 AM

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Driving License



Driving License

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

PASS DATE:

16 Apr 1988
06 Oct 1990
25 May 1992
20 Jun 1995

- Class 2B Motorcycles not exceeding 200 cc
- Class 2A Motor cycles between 201 cc and 400 cc
- Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms
- Class 4 Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms



License No. S76232908

NP 4284

Identification Card



Identification Card



XXXXXXXXXX



NRIC No: S7623590B



Valid till expiry

27-08-2007

APT BLK 28 JALAN LEMPENG #12-06
SINGAPORE 128807

NRIC No: S7623590B

Date: 07/03/2018

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|---------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 3590B |
| Vehicle Details | |
| Vehicle No.: | SKX76A |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 05 Sep 2018 |
| Vehicle Make: | MERCEDES BENZ |
| Vehicle Model: | GLC250 4MATIC COUPE AUTO |
| Primary Colour: | White |
| Manufacturing Year: | 2018 |
| Engine No.: | 27492031465910 |
| Chassis No.: | WDC2533462F442770 |
| Maximum Power Output: | 155.0 kW (207 bhp) |
| Open Market Value: | \$51,815.00 |
| Original Registration Date: | 18 Jun 2018 |
| First Registration Date: | 18 Jun 2018 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$65,267.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 17 Jun 2028 |
| PARF Rebate Amount: | \$48,950.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 17 Jun 2028 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$36,000.00 |
| COE Rebate Amount: | \$28,800.00 |
| Total Rebate Amount: | \$77,750.00 |

The information contained herein is correct as at 05 Sep 2018.

OK

MOTOR CAR (LH)

Left Portion

| NAC | INC | Item | CON | AC | Qty |
|------|--------|-----------------------------------|-----|----|-----|
| 1255 | 995326 | Frt LH Door | SCR | ✓ | |
| 1256 | 995140 | Frt LH Door Protector | | | |
| 1257 | 995104 | Frt LH Door Hinge | | | |
| 1258 | 995142 | Frt LH Door Wing Mirror | | | |
| 1259 | 995102 | Frt LH Door Garnish | | | |
| 1260 | 991593 | Frt LH Door Glass Outer Moulding | | | |
| 1261 | 991588 | Frt LH Door Glass Inner Moulding | | | |
| 1262 | 995103 | Frt LH Door Glass | | | |
| 1263 | 991595 | Frt LH Door Glass Regulator | | | |
| 1264 | 991596 | Frt LH Door Glass Regulator Motor | | | |
| 1265 | 991662 | Frt LH Door Rubber | | | |
| 1266 | 991636 | Frt LH Door Outer Handle | | | |
| 1267 | 991607 | Frt LH Door Inner Handle | | | |
| 1268 | 991625 | Frt LH Door Lock w/Key | | | |
| 1269 | 991624 | Frt LH Door Lock | | | |
| 1270 | 991562 | Frt LH Door Central Lock | | | |
| 1271 | 991675 | Frt LH Door Switch | | | |
| 1272 | 991617 | Frt LH Door Inner Trim Board | | | |
| 1273 | 991568 | Frt LH Door Checker | | | |
| 1274 | 991575 | Frt LH Door Felt | | | |
| 1275 | 991688 | Frt LH Door Wire Harness | | | |
| 1276 | 991683 | Frt LH Door Window Glass Pillar | | | |
| 1277 | 991640 | Frt LH Door Outer Pillar | | | |
| 1278 | 991613 | Frt LH Door Inner Pillar | | | |
| 1279 | 991646 | Frt LH Door Pillar Inner Garnish | | | |
| 1280 | 990554 | Centre Pillar LH | | | |
| 1281 | 990542 | Centre Inner Pillar LH | | | |
| 1282 | 990517 | Centre Pillar Upper Garnish LH | | | |
| 1283 | 990564 | Centre Pillar Lower Garnish LH | | | |
| 1284 | 991670 | Frt LH Door Step Garnish | | | |
| 1285 | 994052 | Rocker Panel LH | | | |
| 1286 | 994049 | Rocker Panel Inner Panel LH | | | |
| 1287 | 994046 | Rocker Panel Garnish LH | | | |
| 1288 | 994055 | Rocker Panel Outer Side Skirt LH | | | |
| 1004 | 991300 | Frt Bumper LH | SCR | ✓ | |
| 1006 | 991325 | Frt Bumper Bracket LH | DL | ✓ | |
| 1007 | 991462 | Frt Bumper Side Retainer | | | |
| 1008 | 991433 | Frt Bumper Reinforcement | | | |
| 1010 | 991468 | Frt Bumper Sponge | | | |
| 1011 | 991427 | Frt Bumper Protector | | | |
| 1014 | 991301 | Frt Bumper Moulding | | | |
| 1015 | 991407 | Frt Bumper Lower Spoiler | | | |
| 1029 | 995153 | Frt LH Headlamp Assy | | | |
| 1031 | 995088 | Frt LH Side Lamp | | | |
| 1096 | 995070 | Frt LH Fender | SCR | ✓ | |
| 1098 | 995147 | Frt LH Fender Lamp | | | |
| 1099 | 995148 | Frt LH Fender Protector | | | |
| | | Frt LH wheel arch | DL | ✓ | |
| | | Frt LH wheel | SCR | ✓ | |

Vehicle No: **SKX 76A**

| NAC | INC | Item | CON | AC | Qty |
|------|--------|-------------------------------------|-----|----|-----|
| 1289 | 995156 | Rear LH Door | | | |
| 1290 | 993282 | Rear LH Door Protector | | | |
| 1291 | 995194 | Rear LH Door Hinge | | | |
| 1292 | 993228 | Rear LH Door Garnish | | | |
| 1293 | 993278 | Rear LH Door Glass Outer Moulding | | | |
| 1294 | 993231 | Rear LH Door Glass Inner Moulding | | | |
| 1295 | 995190 | Rear LH Door Glass | | | |
| 1296 | 993238 | Rear LH Door Glass Regulator | | | |
| 1297 | 995192 | Rear LH Door Glass Regulator Motor | | | |
| 1298 | 993294 | Rear LH Door Rubber | | | |
| 1299 | 993275 | Rear LH Door Outer Handle | | | |
| 1300 | 993250 | Rear LH Door Inner Handle | | | |
| 1301 | 993261 | Rear LH Door Lock | | | |
| 1302 | 993256 | Rear LH Door Inner Trim Board | | | |
| 1303 | 993218 | Rear LH Door Checker | | | |
| 1304 | 993230 | Rear LH Door Glass Channel | | | |
| 1305 | 993242 | Rear LH Door Glass Triangle Garnish | | | |
| 1306 | 993285 | Rear LH Door 1/4 Glass | | | |
| 1307 | 993288 | Rear LH Door 1/4 Glass Rubber | | | |
| 1308 | 993287 | Rear LH Door 1/4 Glass Pillar | | | |
| 1309 | 993305 | Rear LH Door Step Garnish | | | |
| 1310 | 993309 | Rear LH Door Switch | | | |
| 1311 | 994070 | Roof Top Panel | | | |
| 1312 | 994098 | Roof Top Moulding | | | |
| 1313 | 994085 | Roof Top Air-bag | | | |
| 1314 | 994084 | Roof Top Air-bag Sensor | | | |
| 1315 | 994083 | Roof Top Air-bag Control Unit | | | |
| 1143 | 992958 | Rear Bumper | | | |
| 1147 | 992976 | Rear Bumper Bracket | | | |
| 1148 | 993068 | Rear Bumper Side Retainer | | | |
| 1149 | 993045 | Rear Bumper Reinforcement | | | |
| 1151 | 993077 | Rear Bumper Sponge | | | |
| 1153 | 993040 | Rear Bumper Protector | | | |
| 1155 | 993026 | Rear Bumper Moulding | | | |
| 1157 | 993023 | Rear Bumper Lower Spoiler | | | |
| 1163 | 993851 | Rear LH Taillamp | | | |
| 1218 | 993436 | Rear LH Fender | | | |
| 1219 | 993449 | Rear LH Fender Protector | | | |
| 1136 | 990247 | Sticker | | | |

Handwritten signature
 12/9/11

No of Items: 6 Assessor: _____

TOTUM
 WIL
 12/9/11

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|--|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 28 Aug 2018 Edit Reg | | 28 Aug 2018 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|--------------------------|

| CLAIM SUBFOLDER DETAILS | | [Created by adjuster] | | | | | | | |
|---|---|---------------------------------|--|---------|---------|-------------|--------------|------------|-------|
| Insured: | Jeremy Lee Seow Poh (Jeremy Li XiaoBao), ID: S7145510F, Tel: +6596817989 | | | | | | | | |
| Main Claimant: | - | | | | | | | | |
| Vehicle Reg. No.: | SKX76A | Date of Loss: | 23/08/2018 00:00 - :59 [2 Months and 5 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 4096127207SG | Policy/Cover Note No.: | 2100448631 | | | | | | |
| Vehicle Reg. No. (Insured): | EE71J | Policy No. (Claimant): | | | | | | | |
| Repairer: | Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel: | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 06/09/2018] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | View All | Compose Case Mail | | | | | | |
| <ul style="list-style-type: none"> AIG_SG (30/08/2018): Request To Upload TP GIA Report AIG_SG (30/08/2018): No OI GIA Report | | | | | | | | | |
| ALL ASSOCIATED TASKS | | View All | Search Tasks | | | | | | |
| | | Create New Task | Complete | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SKX76A (4096127207SG)
[EE71J]

TP

-

Aug 23 2018 12:00AM
[Jeremy Lee Seow Poh (Jeremy Li XiaoBao)]
Apex Motoring

| Upload Documents | | | Upload Photos | | | Compose New Letter | | | Upload Video | | | Upload Audio | | | View | View in Browser |
|----------------------|-----------------|---|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|------------|-------------------------------------|
| Photos/Images | | | | | | | | | | | | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | | | | Thumbnail | Print |
| 1 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 2 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 3 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 4 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 5 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 6 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 7 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 8 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 9 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 10 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 11 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 12 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 13 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 14 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 15 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 16 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 17 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 18 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 19 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 20 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 21 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 22 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 23 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 24 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 25 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 26 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 27 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 28 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 29 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 30 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 31 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 32 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 33 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| 34 | 04/09/18 16:54 | General View | | | | | | | | | | | | | | <input checked="" type="checkbox"/> |
| Documentation | | | | | | | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | | | | | | | | | | | | Thumbnail | Print |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 11/09/18 10:09 | TP GIA |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18015690/T1Z4D3E2

Date: 17/09/2018

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 2100448631 |
| Claimant Vehicle No : | SKX76A | Insured Vehicle No : | EE71J |
| Date of Loss: | 23/08/2018 | Nature of Claim: | TP |
| | | Claim No: | 4096127207SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SKX76A | | |
| Make & Model: | MERCEDES-BENZ GLC250, 2.0 4MATIC COUPE (A) | Engine No: | 27492031465910 |
| Reg. Date: | 18/06/2018 (Man. Year: 2018) | Chassis No: | WDC2533462F442770 |
| Colour: | White | Odometer: | 3958 km |
| Engine Capacity: | 1991 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 235/55 R19 | Rear Tyre Size: | 235/55 R19 |
| Front Left Side: | Hankook 6 mm | Rear Left Side: | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | |
|-----------------------------|------------|---|
| Date of Assignment: | 28/08/2018 | |
| Date Inspected: | 29/08/2018 | Inspected At: Apex Motoring 25 Kaki Bukit Road 4, #01-55 Synergy @ KB Singapore 417800 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---------------------------|-----|----------|------------------------|-----------|-------------|-------------|
| 1 | 1 | | *FRT LH DOOR | Scratched | 0.00 F | *-F |
| 2 | 1 | | *FRT BUMPER LH | Scratched | 0.00 F | *-F |
| 3 | 1 | | *FRT BUMPER BRACKET LH | Dislodged | 0.00 F | *-F |
| 4 | 1 | | *FRT LH FENDER | Scratched | 0.00 F | *-F |
| 5 | 1 | | *FRT LH WHEEL ARCH | Dislodged | 0.00 F | *-F |
| 6 | 1 | | *FRT LH WHEEL | Scratched | 0.00 F | *-F |
| Total Parts (\$\$) | | | | | 0.00 | 0.00 |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >