

Your Ref: RT/EK/15/2019/zx

Date: 18th Oct 2021

Our Ref: CS1/LAW21001698/Dqd3e2

M/s Tan Chin Hoe & Co

24 Raffles Place

#24-01 Clifford Centre

Singapore 048621

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: PC 2925M**INSURED VEHICLE: PC 3087A****ACCIDENT DATE: 16/12/2017**

We thank you for your instruction on 03/02/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of PC 2925M from M/s Chartered Auto Assessors.
- b) Survey report by FormTeam Consultancy Pte Ltd with colour photographs.
- c) Final Repair Bill of PC 2925M from M/s Precise Auto Service.
- d) Singapore Accident Statement and Police Report of Vehicles PC 2925M and PC 3087A
- e) Colour damaged vehicle photographs of PC 2925M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: PC 2925M
Make & Model	: Nissan NV350 (HI-Roof)
Chassis Number	: JN1UC4E26Z0001815
Year of Registration	: 2014
Engine Capacity	: 2500 cc

- 2. We recommend that the repairs of the entire damage require about 35 (Thirty Five) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.