

Service Request Details

Claim	S1M031CY
Reference	CS3/ASM21001718/Gtf3
Loss Date	January 13, 2021
Report Date	Jan 26, 2021 9:20:34 AM
Request Date	February 4, 2021
Due Date	February 4, 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pre-Repair Survey

Actions

Next Step Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle	FBM6463R
Registration #	
Make	TPVD Yamaha
Model	NMAX155

Service Address

...

Primary Contact/Insured

COMFORT
 TRANSPORTATION PTE LTD 383 SIN MING DRIVE,
 575717, Singapore
 65551188

Claim Handler

TAN
 Jun Hong junhong.tan@axa.com.sg

Additional Instructions

1

- [Messages](#)
[Invoices](#)
[History](#)
[Documents](#)
[Assessment](#)
[Metrics](#)
[Notes](#)

New Message

TYPE	SENT	FROM	SUBJECT	BODY	
	2/9/21 2:20 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	IA UPLOADED	HI IA UPLOADED. PRS CASE REGRDS DENISE	
	2/4/21 6:19 PM	TAN Jun Hong	Re:Kindly assist to provide the workshop details thanks.	Block 4003 Ang Mo Kio Avenue 10, Industrial Park 1...	
	2/4/21 11:38 AM	LKK AUTO CONSULTANTS PTE LTD (TP)	Kindly assist to provide the workshop details thanks.	Kindly assist to provide the workshop details than...	