

ASS. REC. BY:

REF: CS3/ASM21001719/Gvf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Tan Jun Hong of AXA Date/Time: 3/2/2021 1:42 PM

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBM 1430T Insured: SHB 3995D

at Workshop m/s SS Motoring Tel: 9233 3336

of Blk 1084 Serangoon Road Singapore 328186

Policy No: Claim No: S1M031G1

Sum Insured: Excess:

Make of Veh: D.O.A. 12-01-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP"

H.O.D. Endorsement:

Date/Time: 5-2-21 10.16A.M Person Contacted: SAM Vehicle IN ☒ OUT

Date/Time	Action/Instruction (☒) Estimate
	FBM 1430T- ☒
	SHB 3995D - CS/FCI15017427/Aqbc2 DOA :12/10/2015
9/2/21	Send IA via Smart Claim
9/2/21	Submit PRS, repair range \$2,000-\$3,000 (3 days)