



TP CLAIM - EQ
SURVEY: 16/03/21
UKK - STEVE

VEHICLE NO : SMQ 5183D

MODEL : HA/CERATO 1.6 A EX

WIP : 27853

Material	:	\$	<u>2,587.00</u>
Labour	:	\$	<u>3,390.00</u>
Sub-Total	:	\$	<u>5,977.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>5,977.00</u>
GST 7%	:	\$	<u>418.39</u>
Grand Total	:	\$	<u>6,395.39</u>
Finalise By/Date : <u>Larry on 07/06/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS + 2 days (wk end)

* TP VEHICLE NO : SFA6388R

* GIA search fee \$2.00

* claim loss of RENTAL.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
YANG KAYMOND	Cust No/Name	/YANG KAYMOND
BLK 84B LORONG 2 TOA PAYOH	Reg No/Reg Date	SMQ5183D*ECB1/ 21/11/2019
#25-303	Date In/Mileage	16/03/2021/ 16893
SINGAPORE 312084	Chassis/Package	KNAF3416MK5045246 /#
Contact No Mobile: 97551133	Engine No	G4FGKH737941
16/03/2021	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00080	Cash	07/06/2021/ 11:40	TLE	884 / Lauro Songcuan	27853		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1280.00 ✓
RENEW REAR BUMPER AND BOOTLID							
E PNT98000							1100.00 ✓
SPRAY PAINT REAR BUMPER, REAR END PANEL AND BOOTLID							
E PNT88000							320.00 ✓
REMOVE & REFIT BOOTLID COMPONENTS							
A 54900099							50.00 ✓
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							280.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
E PNT88000							100.00 ✓
REMOVE & REFIT REVERSE SENSOR							
M SUNDRY							40.00 ✓
SUPPLY C&C BADGE							
M SUNDRY							20.00 ✓
SUNDRIES							
E PNT88000							200.00 X
REPAIR REAR END PANEL → Supp.							
X COVER-RR BUMPER ✓				1.00	651.00	00.00	651.00 ✓
X COVER-RR BUMPER LWR ✓				1.00	241.00	00.00	241.00 ✓
X BEAM-RR BUMPER ?				1.00	318.00	00.00	318.00
X PANEL ASSY-TRUNK LID ✓				1.00	1297.00	00.00	1297.00 ✓
X LOGO ASSY-KIA SUB ✓				1.00	32.00	00.00	32.00 ✓
X EMBLEM-CERATO ✓				1.00	28.00	00.00	28.00 ✓
X CLIP → Supp.				10.00	2.00	00.00	20.00 X
Z TEXT							
TP CLAIM EQ - SFA6388R							
DOA: 21/01/2021							
SURVEY: STEVE (LKK) 16.03.2021							
04 DAYS							
Guarantee Your Warranty, Maintain with Cycle & Carriage!							

Parts	2,587.00	Nett	5,977.00
Labour	3,330.00	7% GST on	418.39
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	6,395.39
Sundry/Others	60.00		
Total(w/o GST)	5,977.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : EQ

Supplementary For Registration No.: SMQ 5183 D

	<u>Materials</u>	<u>Cost \$</u>
1	Clip (10 pcs)	20.00 / nec
	<u>Labour</u>	
1	Repair Rear End panel	200.00
		220.00
	7% GST	15.40
	Total	235.40

1
Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SM05183DWIP: 27853 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	BEAM-RR Bumper	(?) SUPP		✓ RR	
2	Bumper clip (10)	? / SUPP		✓ MC	
3		? / SUPP			
4	Repair End Panel \$900	? / SUPP		✓	Stew 17/9/21
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CERATOSURVEYOR: STEVE



HOME

Online



CERATO/FORTE../2019/G 1.6 MPI..

VCI




Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0241

VCI Ver.

02.51

ECU Ver.


M-E-K-01-00-0182

OS Ver.

Android 10

Fault Code Searching

Rescan Erase All DTC Go to DTC Save



System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0241	VCI Ver.	02.51
ECU Ver.	M-E-K-01-00-0182	OS Ver.	Android 10