

ASS. REC. BY:

REF: C72 / 21001742/KV

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Link

of _____

Insured: GBC 8179B

Policy No. DMCVSNW00121022000

Claims No. SNM21D2006S2 / CO3 / CHNGPW

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFTJ99888 Yr Regn: 06, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Toy Piente c.c 1496

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 44685 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: M14F7 2814330 0035285

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front Rear

R/Bal. 3 mm R/Bal. 2 mm

L/Bal. 3 mm L/Bal. 2 mm

D.O.A. 2/12/21 D.O.I. 5/2/2021

Survey held at _____

Des. of Damages (Frt) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
26/3/21	Final fig \$7441.25 confirmed by email (Red 1243.35, 14%)

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

2) 26/3/21-Typist

Days Of Repair: 10

Resurvey No. of Trlp: 3

Survey Fee:

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Transportation: \$ - RS. \$

Fuel

Others

TOTAL

Report Format : Merimen

Lump Sum / I.B.I. (\$ 7441.25)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 960A

Vehicle Details

Vehicle No.: SFJ9988S
Vehicle to be Exported: Yes
Intended Deregistration Date: 03 Feb 2021
Vehicle Make: TOYOTA
Vehicle Model: SIENTA 1.5 CVT ELEGANCE
Primary Colour: Grey
Manufacturing Year: 2018
Engine No.: 2NRX342980
Chassis No.: MHFZ28H3300055285
Maximum Power Output: 79.0 kW (105 bhp)
Open Market Value: \$18,899.00
Original Registration Date: 26 Jun 2018
First Registration Date: 26 Jun 2018
Transfer Count: 0
Actual ARF Paid: \$18,899.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Jun 2028
PARF Rebate Amount: \$14,174.00

Intended COE Rebate Details

COE Expiry Date: 25 Jun 2028
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$34,110.00
COE Rebate Amount: \$25,222.00
Total Rebate Amount: \$39,396.00

The information contained herein is correct as at 03 Feb 2021

OK



Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: 20-MT103980-R02 (Private Motor Car)

1. **Index Mark and Registration Number of Vehicle** SFJ9988S **Chassis No.:** MHFZ28H3300055285
2. **Name of Policyholder** LOW CHEO TEE
3. **Effective date of the Commencement of Insurance for the purposes of the Act** 26/06/2020
4. **Date of Expiry of Insurance** 25/06/2021
5. **Persons or Class of Persons entitled to drive***
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. **Limitations as to use***

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: 0953DDB

Insurance Plan:	Comprehensive Other Workshop Plan	
Limit for total loss or theft:	Prevailing Market Value	
Policy Excess:	Excess - All Claims	SGD 1,500
	Windscreen Excess	SGD 100

Tokio Marine Insurance Singapore Ltd.

Authorised Signature

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/02/2021 17:42 (SGT)
Date of Accident	02/02/2021 18:20 (SGT)
Exact Location of Accident	Toa Payoh Industrial Park, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFJ9988S
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Low Cheo Tee
NRIC No	SXXXX960A
Email Address	benson.teo@teoholdings.com
Mobile Phone No	(Phone) +65-91913466
Alternative Phone No	(Office) +65-63830893

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Sienta
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	20-MT103980-R02
Cover Note Number	-

DRIVER

Name of Driver	Teo Ek Khoon
NRIC No	SXXXX616G
Date Of Birth	09/01/1951
Occupation	Outdoor

Date Of Driving Pass	09/01/1975
Driving experience	46 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-83181951
Alt. Phone Number	-
Email Address	benson.teo@teoholdings.com
Address	Blk 455C Ang Mo Kio Street 44 #10--29
Address complement	-
Postcode	563455
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	Yes
Number of vehicles involved in the accident	5
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

FOREIGN VEHICLE 1

Vehicle Registration Number	JTV9427
Vehicle Category	Motorcycle

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Ang Mo Kio South Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18004519999
Alt. Police Station Phone No	(Fax) +65-65535679
Police Station Address	81 Ang Mo Kio Ave 3 Singapore 569929
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan / police report no. T/20210203/2019

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC8179B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	JTV9427
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Motorcycle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	GBJ7207Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	GBC81B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-




SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

 Policyholder Signature / Date & Time	 Driver's Signature (if driver is not the policyholder) / Date & Time	 Witnessed by Reporting Centre Personnel Jenny Lim
Sketch Plan 		A - SFJ 9988S B - GBC 8179B C - JTV 9427 D - GBJ 7207Z E - GBC 81 B

Describe Circumstances of the Accident

Please refer to Police Report No = T/20210203/2019

Declaration


**SINGAPORE
POLICE FORCE**


Police Station: 3311 (1) (1)
 Sgt Mr. K. S. P. N. R. C.
 51 Ang Mo Kio Avenue 1, SINGAPORE 069620
 Tel No. 1800 4519229

Report No: SL0321230005

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 03/02/2021 10:03	File Report No E/20210202/0105	Station Diary No 22
-------------------------------------------	-----------------------------------	------------------------

Informant's Particulars

Name of Informant TEO EK KHOON			Address APT BLK 455C ANG MO KIO STREET 44 #10-29 SINGAPORE 563455		
ID Type / ID No NRIC NO / S 12853160			Contact No. Home/Office: Mobile 83181951		
Nationality SINGAPORE CITIZEN			Ema.		
Sex Male	Age 70	Date of Birth 09/01/1951	Type of Informant Driver		
Race Chinese			Language Institution / School Name		
Occupation Facilities Manager			Driving Licence Information Class: 3 Date of Expiry		

General Information of the Accident

Type of Accident	Injury Attended by Police	Drink Drive No	Date/Time of Accident 02/02/2021 18:20	Type of Location Straight Road
------------------	------------------------------	-------------------	-------------------------------------------	-----------------------------------

Location

TOA PAYOH INDUSTRIAL PARK

Weather Clear	Road Surface Dry	Road Speed Limit
Traffic Flow One Way	Traffic Control Not Controlled	Traffic Volume Light
Type of Collision Between Moving Vehicles - Head To Side		Anyone conveyed by ambulance No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC3173B	Van				Seriously Damaged	0
GBC81B	Van				Slightly Damaged	0
CBJ7297Z	Van				Slightly Damaged	0
JFV942T	Motorcycle				Slightly Damaged	0
SFL9988S	Car				Seriously Damaged	0



SINGAPORE
POLICE FORCE



1002100052019

Police Station Of Origin
Ang Mo Kio South N.P.C.
81 Ang Mo Kio Avenue 3 SINGAPORE
569979
Tel No. 1800-4519999

Page 11
Reference: 1002100052019

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LOW TECK HUI	ID No.	G6709741L
Related Vehicle	GBC8179B (Van)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	TEO EK KHOON	ID No.	S1085618G
Related Vehicle	SFJ9988S (Car)	Contact No.	83181951
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On 02/02/2021, at about 6:20pm, I was driving my vehicle SFJ9988S at Toa Payon Industrial Park, at the junction of Blk 3, 4, 5 and 6. I was driving straight and proceeded across the junction. When I was at the junction, another vehicle GBC8179B suddenly dashed and drove straight. I could not brake on time and hit his vehicle. As a result of the collision, his vehicle hit 2 other van and 1 motorcycle, all of which were parked with no one inside. My vehicle's whole front was damaged and the left side of the vehicle (GBC8179B) was damaged. At that point of time, my heart was beating very quickly and ambulance came to make a check on me. Traffic police was also at scene. I have in-car video and I have handed over the video to the traffic police officer. I do not have the particulars of the other 3 vehicles involved in the accident as the owners were not there.



SINGAPORE
POLICE FORCE



1/20190301016

Police Station Of Origin
Ang Mo Kio South N.P.C.
31 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No. 1800-4519999

Page 5
Report No. SL0321230005

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report

Sgt 2 KOH WEI JUN JONES

Signature Of Informant

Signature Of Interpreter
Not applicable

Date/Time
03/02/2021 16:03

Officer In Charge Of Case
IP: G11

Sr Staff Sgt LIM ENG KUAN CLARENCE
Contact No. 85476200

Classification Of Case

SN: 34

Authentication Stamp
IP: G11



Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: TP-GBC 8179B
 Repairer Reference: 71859
 Date calculated: 04/02/2021 3:01 PM

Full Report
 Registration: SFJ 9988S
 Printed: 04/02/2021 3:01 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GBC 8179B	Date of Incident:	02/02/21
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	SIENTA		
Sub Model:	ELEGANCE		
Model Sheet Number:	70 T2 17		
Registration:	SFJ 9988S		
VIN number:			
Odometer:	44685		
Model Specs			
FROM 06/2018	AIR CONDITIONING	LED HEADLAMP	
BONNET INSULATION	1.5 LTR 79 KW	TYRES 195/50 HR 16	
TWO COAT METALLIC	PREPARE OFF VEHICLE		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged By: **CVT AUTOMATIC**
 Signature: _____
 Date: _____

Not Authorized
Resurvey By paint
10 days

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B040	ADJUST HEADLAMPS		2.0	8.40
B140	RENEW LOWER FRONT PANEL		7.0	29.40
NO NUMBER	RENEW LEFT SIDE MEMBER CLOSING PANEL		20.0	84.00
NO NUMBER	RENEW RIGHT SIDE MEMBER CLOSING PANEL		20.0	84.00
B110	RENEW L/F WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WING, CONVERT ATTACHED PARTS		5.0	21.00
B110	RENEW R/F WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WING, CONVERT ATTACHED PARTS		5.0	21.00
B010	R + R FRONT BUMPER		5.0	21.00
B020)	RENEW FRONT BUMPER (REMOVED) INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		4.0	16.80
B010)	R + R FRONT BUMPER REINFORCEMENT		3.0	12.60
B040)	R + R LEFT HEADLAMP		1.0	4.20

Code	Description	WU	Price SGD
B040)	R + R RIGHT HEADLAMP	1.0	4.20
B040)	RENEW HEADLAMP (REMOVED)	1.0	4.20
530051	RENEW BONNET INCLUDES: R + R BONNET, ATTACH PARTS ASSEMBLE AND IF NEC RENEW	3.0	12.60
B080	RENEW BONNET HINGE/S	1.0	4.20
B125	RENEW FRONT LOCK CARRIER	5.0	21.00
B085	R + R AIR GRILLE	2.0	8.40
M010)	RENEW AIR CON CONDENSER	2.0	8.40
M010	DRAIN AIR CONDITIONING	3.0	12.60
002889	REFILL AIR CONDITIONING	7.0	29.40
M020	R + R RADIATOR INCLUDES: BLEED COOLING SYSTEM	5.0	21.00
160101)	R + R UPPER RADIATOR HOSE	2.0	8.40
M020)	RENEW RADIATOR (REMOVED)	2.0	8.40
111261)	DETACH AND REFIT R/F ENGINE MOUNT	2.0	8.40
111261)	R + R RIGHT FRONT ENGINE MOUNT	3.0	12.60
NO NUMBER	DIS-/ASS ENGINE SUPPORTS	5.0	21.00
NO NUMBER	RENEW R/ENGINE CARRIER FLANGE	3.0	12.60
1207	L/F SIDE MEMBER REPAIR	60	100.0* ✓ 420.00
1208	R/F SIDE MEMBER REPAIR	60	100.0* ✓ 420.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		31.90	319.0
Total of Labour			1,339.80

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
Paint Work SYSTEM AZT Time Basis 10 WU/h			
	BONNET NEW PART PAINTING	12.0	
	L/F WING NEW PART PAINTING	9.0	
	R/F WING NEW PART PAINTING	9.0	
	FRONT PANEL CPL SURFACE PAINT	6.0	
	L/F S-MEMBER REINF SURFACE PAINT	4.0	
	FRONT BUMPER NEW PART PAINT K1R	13.0	
	L/F SIDE MEMBER SURFACE PAINT	5.0	
	R/F SIDE MEMBER SURFACE PAINT	5.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	28.90
0741	L/F WING NEW PART PAINTING	17.03
0742	R/F WING NEW PART PAINTING	17.03
1009	FRONT PANEL CPL SURFACE PAINT	12.45
1285	L/F S-MEMBER REINF SURFACE PAINT	1.25
0281	FRONT BUMPER NEW PART PAINT K1R	62.98
1207	L/F SIDE MEMBER SURFACE PAINT	4.98
1208	R/F SIDE MEMBER SURFACE PAINT	4.98

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	42.00 SGD/h			
Time Paint			63.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	9.30	93.0	390.60

Material Cost - Paint		Price SGD
New Part Painting		62.96
New Part Painting - Plastic K1R		62.98
Surface-/Blend Paint		23.66
Material-constant Metal Preparation		28.60
Material-constant Plastic		9.00
Total		187.20

Spare Parts

					prices as at 2015-06-01/01	
Code	Description	Part Number	Part Source			Price SGD
0471	BONNET	53301 0D260	Original	BM ✓		220.00
0493	BONNET LOCK	53510 0D640	Original	DI ✓		55.00
4465	CONDENSER	88460 0D390	Original	BM ✓		385.00
9987	COOLANT/ANTIFREEZE	NO NUMBER	Original	MC ✓		22.00
8933	ENGINE SUPPORT	12372 0Y060	Original	SVC BT ✓		120.00
0474	FRONT BONNET SEAL	53395 0D040	Original	DI ✓		25.00
1006	FRONT BRACE PANEL	RENEW	Original	BM ✓		70.00
0281	FRONT BUMPER	52119 0U928	Original	BT/CD ✓		165.00
1009	FRONT PANEL CPL	53201 0D200	Original	BM ✓		250.00
1004	FRT BPR TOW COVER	RENEW	Original	DI ✓		20.00
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	Original	MC ✓		20.00
0340	FRT BUMPER REINF	52021 0D140	Original	BM ✓		130.00
0341	FRT CTR UPP BRACKET	52521 0D020	Original	BM ✓		50.00
7774	FRT UPP RAD HOSE	16571 0Y100	Original	SM ✓		25.00
0410	GRILLE	53101 0D700	Original	DI ✓		220.00
0475	L/BONNET HINGE	53420 0D642	Original	BM ✓		30.00
1191	L/F AIR DUCT	53286 0D310	Original	SM ✓		60.00
0317	L/F BUMPER BRACKET	52144 0D120	Original	DI ✓		35.00
1277	L/F OUT SIDE MEMBER	57114 0D050	Original	BM ✓		50.00
1285	L/F S-MEMBER REINF	57202 0D051	Original	BM ✓		70.00
0841	L/F WHEELHOUSE COVER	53876 0D410	Original	DI ✓		70.00
0741	L/F WING	53812 0D220	Original	BM ✓		180.00
0789	L/F WING CLAMP KIT	USE SINGLE PARTS	Original	MC ✓		15.00
0993	L/UPP RADIATOR BRKT	53203 0D090	Original	DI ✓		35.00
0561	LEFT HEADLAMP ASSY	81150 52K30	Original	CD ✓		1,150.00
0431	MANUFACTURER BADGE	75301 0D160	Original	MC ✓		35.00
0476	R/BONNET HINGE	53410 0D642	Original	BM ✓		30.00
0318	R/F BUMPER BRACKET	52143 0D120	Original	BM ✓		35.00
0256	R/F LOWER BUMPER LID	81481 0D280	Original	DI ✓		60.00
1278	R/F OUT SIDE MEMBER	57113 0D050	Original	BT ✓		50.00
0742	R/F WING	53811 0D220	Original	BM ✓		180.00
8642	R/RUBBER BUSH	12305 0Y060	Original	SM ✓		100.00
0994	R/UPP RADIATOR BRKT	53202 0D080	Original	DI ✓		35.00
7761	RADIATOR CPL	16400 0Y130	Original	SM ✓		420.00
0562	RIGHT HEADLAMP ASSY	81110 52K30	Original	MC ✓		1,150.00

Code	Description	Part Number	Part Source	Price SGD
1015	UPP RADIATOR COVER	53289 0D140	Original	85.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			5,652.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			5,752.00

Extras

Code	Description	Price SGD
1000	CHK/ERASE FAULT CODE	80.00*
1001	WHEEL ALIGNMENT	60.00*
1002	FRONT NUMBER PLATE	35.00*
1003	FRONT BRACE PANEL	70.00*
1005	AIR CON GAS	50.00*
	Total Extras	295.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	5,652.00	
Total Parts	100.00	5,752.00
Labour Time Base 10 WU/h		
Total 319.0 WU X 42.00 SGD/h	1,339.80	
Total of Labour		1,339.80
Total Of Extras		295.00
Paint Work Time Base 10 WU/h		
Labour Cost 93.0 WU X 42.00 SGD/h	390.60	
Material Cost	187.20	
Total Paint Including Material		577.80
Repair Cost Excludes GST		7,964.60
GST (+7.0%)		557.52
Repair Cost Included GST		8,522.12

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

DETAILS

SUPPLEMENTARY

Price

Code: MRM-SG Version: 1.0 (Last Synchronised: 18 Feb 2021)
 M1-MPV TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue Merimen Singapore 1.0)
 Repairer's (Price-denominated Standard List)

Note: (Unsubmitted, no print-code for SFJ9988S)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Note: Items/values not in reference catalogue are prefixed with an asterisk *

Items on Parts

Part No.	Particulars	%Disc	%Depr	Amount
	*WASHER CONTAINER	0.00	0.00	<i>Net</i> *65.00 F ✓
	*COND TUBE	0.00	0.00	<i>Ry</i> *165.00 F ✓
	*RADIATOR SHROUD	0.00	0.00	<i>8-1</i> *100.00 F ✓
	*R/F AIR DUCT	0.00	0.00	<i>CR</i> *40.00 F ✓
	*RAD S/SEAL LOWER	0.00	0.00	<i>8-1</i> *40.00 F ✓
	*RAD S/SEAL LOWER LH	0.00	0.00	<i>Net</i> *40.00 F ✓
	*BONNET STOPPER	0.00	0.00	<i>h.s</i> *10.00 F ✓
	*AIR FUEL SENSOR	0.00	0.00	<i>R</i> *180.00 F ✓
	*R/F S-MEMBER REINF	0.00	0.00	<i>R1</i> *80.00 F ✓
Total Parts (S\$)				720.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS