

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



NEW AND AND THE PARTY OF A PER ATTIVE LTD. D. () NO (NO A PARTY OF A PARTY O						
NTUC INCOME INSURANCE CO-OPERATIVE LTD R				NS/INC21001749/1	1π3q2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	10-03-2021 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	FBQ 3773U		nspected	SHD 7204S	
	Policy No.	5112953764-01		 age (\$)	0.00	
	Claim No.	MT/1120263-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	04/02/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMHU096465	Coloui	ſ	BLUE	
	Odometer	478213	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST	LAKE	6 mm	
	L/H Front Tyre	205/60 R16	WEST	LAKE	6 mm	
	R/H Rear Tyre	205/60 R16	WEST		6 mm	
	L/H Rear Tyre	205/60 R16	WEST	_AKE	6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/02/2021	Inspec	tion Date	04/02/2021	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					