# **SINGAPORE ACCIDENT STATEMENT**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

- and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **ACCIDENT STATEMENT**

Date of Submission 05/02/2021 15:46 (SGT) Date of Accident 04/02/2021 14:55 (SGT) Exact Location of Accident Balestier Rd, Singapore Additional Location Information TOWARDS LAVENDER STREET (AFTER MC NAIR ROAD) Country/State of Loss Singapore

# **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SJK3313B

#### INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner LAI LIN YUEN NRIC No. SXXXX480A Email Address beehiangseafood@gmail.com Mobile Phone No (Phone) +65-83994413 Alternative Phone No +65-83994413

#### VEHICLE PARTICULARS

Manufacturer Mercedes Model C200k Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to

your vehicle? No - Claiming third party Private car

Vehicle Category

## INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance Type of Coverage Comprehensive Fleet Policy Policy Number DMPCSNW00027052008 Cover Note Number

# DRIVER

Name of Driver LAI LIN YUEN NRIC No SXXXX480A Date Of Birth 12/06/1972 Occupation Indoor

Date Of Driving Pass 12/02/2005 Driving experience 16 YEARS Gender Female Mobile Number (Phone) +65-83994413 Alt. Phone Number +65-83994413 Email Address beehiangseafood@gmail.com Address BLK 60 GEYLANG BAHRU #08-3313 Address complement Postcode 330060 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No **DETAILS OF POLICE ACTION** Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLEASE REFER TO SKETCH AND ATTACHMENT ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number Vehicle Manufacturer Vehicle Model	GBE9765S -
V 1: 1 V : .	-
	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-

Nature Of Damage	-
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_

# INJURED PERSONS DETAILS

# INJURED 1

Name of injured person	LAI LIN YUEN
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	NECK AND BODY PAIN
Injured person in which vehicle?	SJK3313B
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Driver's Signature (f driver is not the policyholder) / Date & Time

Sketch Plan

A= SJK 3313B

B= 6BE 9765S

Balestiev Road to wavels

Lavendev Street

(After Mc Nair Road)

		/
	/	
	Refer to attached	
	/	
/		
claration		
to device the formation of the		
e declare the foregoing particulars as	e true in every respect.	
		/ / /
me "		d admin
I A-X	200100	41/ (16/14/16)1

On 04.02.2021 at about 14:55 hours along Balestier Road towards Lavender Street (After Mc Nair Road). I was travelling straight on lane 3 along the above mentioned location and when the front vehicle slowed down and stopped, hence I followed suit.

Suddenly, I heard a loud bang and felt an impact from behind. When I alighted, I realised it was vehicle (B) that collided onto the rear portion of my vehicle (A).

Vehicle (A): SJK 3313B

Vehicle (B): GBE 9765S

Mus.















