

ASS. REC. BY:

REF:

CC4/FWD 2100 1764/Ripa3

065H

COE XPRY: 2024/SEP

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SW 5489Bat Workshop m/s XINYA  
of 1002 BUKIT MERAH LN 3 #01-75Insured: FWD

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 25K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SW 5489BYr Regn: 2009 SEP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA ALTIS 1.6Ac.c. 1598Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 241673

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRO532061061 S3042

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

WESTLAKE

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 02/02/2021D.O.A. 08/02/2021Survey held at XINYA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Int - 14K

Date/Time, File Pass to?

☐ : Prelt. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Rep. Format: \_\_\_\_\_

Lump Sum / L.S. / \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

# XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 04-Feb-20

Address : MR TEO AH KOW  
BLK 412A FERNVALE LINK  
#09-23  
SINGAPORE 791412

Reference : TP 1272/02/21  
Vehicle No : SJW 5489B  
Make/Model : TOYOTA ALTIS  
Insurance Co. : NTUC

## RE : QUOTATION TO SJW 5489B FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>AMT \$</u>
1) FRONT BUMPER <i>de</i>	1	\$ 581.70
2) FRONT BUMPER RETAINER RH <i>ne</i>	1	\$ 144.30
3) FRONT FENDER RH <i>lt</i>	1	\$ 712.90
4) FRONT FENDER COWLING RH ?	1	\$ 199.85
5) HEADLAMP RH <i>scr</i>	1	\$ 608.80
6) TYRE RIM <i>scr</i>	1	\$ <del>596.50</del> 300 S/N
7) BUMPER/ FENDER CLIPS <i>ne</i>	10	\$ 55.00
8) BONNET <i>repair</i>	1	\$ 1,041.50
LIST PRICE TOTAL		\$ 3,940.55
LESS DISCOUNT 25%		\$ 985.14
LIST PRICE TOTAL AFTER LESS		\$ 2,955.41
NETT PRICE TOTAL		\$0.00
TOTAL PARTS COST		<div style="border: 1px solid black; padding: 2px;">\$2,955.41</div>

## LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER, FENDER, HEADLAMP AND PANEL BEAT & ALIGN.	\$ <del>800.00</del> 400 (4 DAYS)
2)	TO PUTTY & SPRAY PAINT FRONT BUMPER & BONNET AND OTHER AFFECTED AREA.	\$ 600.00 (3 PANELS)
3)	TO CHECK & RECTIFY WIRING AND FOCUS HEADLAMP	\$ <del>80.00</del> 30
4)	TO REPLACE TYRE RIM AND BALANCING.	\$ 50.00

5)

TO COMPUTER WHEEL ALIGNMENT

\$ ~~80.00~~ 60

LABOUR TOTAL

\$ 1,610.00

TOTAL ESTIMATED REPAIR COST

\$ 4,565.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Repair  
Hf 90010068  
5 days  
4/5  
08/02/2021 @ 1110  
Rey after repair

mm  
RUBAL  
mm  
100

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	03/02/2021 10:29 (SGT)
Date of Accident	02/02/2021 17:24 (SGT)
Exact Location of Accident	Anson Rd, Singapore
Additional Location Information	TOWARDS MAXWELL ROAD
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW5489B
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	AH KOW @ TEO AH KOW
NRIC No	SXXXX065H
Email Address	goldenway.construction@gmail.com
Mobile Phone No	(Phone) +65-96774100
Alternative Phone No	+65-96774100

## VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire

## INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5112926098-01
Cover Note Number	-

## DRIVER

Name of Driver	AH KOW @ TEO AH KOW
NRIC No	SXXXX065H
Date Of Birth	08/06/1955
Occupation	Outdoor



Date Of Driving Pass ..... 19/08/1976  
 Driving experience ..... 44 YEARS AND 6 MONTHS  
 Gender ..... Male  
 Mobile Number ..... (Phone) +65-96774100  
 Alt. Phone Number ..... +65-96774100  
 Email Address ..... goldenway.construction@gmail.com  
 Address ..... BLK 412A FERNVALE LINK #09-23  
 Address complement ..... -  
 Postcode ..... 791412  
 Is the driver the policyholder? ..... Yes  
 If No, Relationship of the Driver with the Insured ..... -  
 Does Driver Own Other Vehicles? ..... No  
 Vehicle Registration Number of Other Vehicle Owned by Driver ..... -  
 Insurance Company of Other Vehicle Owned by Driver ..... -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident ..... Side Swipe  
 Weather Conditions ..... Clear  
 Road Surface ..... Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? ..... No  
 Number of vehicles involved in the accident ..... 2  
 Was anybody injured in the Accident? ..... No  
 Was any injured conveyed to hospital by ambulance? ..... -  
 Was any other material or property damaged? ..... Yes  
 Number of Passengers (Including Driver) ..... 2  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? ..... No

#### PASSENGER 1

Name ..... UNKNOWN  
 Gender ..... Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? ..... No  
 Was notice of intended Prosecution given? ..... No  
 If yes, against whom? ..... -

#### CIRCUMSTANCES OF ACCIDENT

#### PLEASE REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment? ..... Yes  
 Was there any video captured by Car Camera? ..... No  
 Was there any audio recorded? ..... No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number ..... SJK8478B  
 Vehicle Manufacturer ..... -  
 Vehicle Model ..... -  
 Vehicle Variant ..... -  
 Vehicle Colour ..... -  
 Vehicle Category ..... Private car  
 Name of Driver ..... MR HENG  
 Contact Number ..... (Phone) +65-87543582


Address ..... -  
Address complement ..... -  
Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### Skech Plan




### Describe Circumstances of the Accident


I had moved on from Anson Road as traffic light was green moving into junction sign to turn into Maxwell Rd as usual pedestrian will be moving through slowly. While moving slowly another car came from my right and hit onto my right hand front I had a shock and stopping car.

### Declaration

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	065H

Vehicle No.:	SJW5489B
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Feb 2021
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4924854
Chassis No.:	MR053ZEE106153042
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	03 Sep 2009
First Registration Date:	03 Sep 2009
Transfer Count:	4
Actual ARF Paid:	\$17,853.00

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

COE Expiry Date:	02 Sep 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,743.00
COE Rebate Amount:	\$10,518.00
Total Rebate Amount:	\$10,518.00

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Feb 2021

OK

Silver





Merimen e-Claims



Used 2009 Toyota Corolla Altis 1.6



mart.com/used\_cars/info.php?ID=940071&amp;DL=3004

## ► Toyota Corolla Altis 1.6A (COE till 10/2024)

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price \$25,800

Depreciation ⓘ \$7,010 /yr

Reg Date 15-Oct-2009  
(3yrs 8mths 6days COE left)

Mileage 122,000 km (10.8k /yr)

Manufactured ⓘ 2009

Road Tax ⓘ \$890 /yr

Transmission Auto

Dereg Value ⓘ \$11,258 as of today (change)

OMV ⓘ \$17,853

COE ⓘ \$15,287

ARF ⓘ \$17,853

Engine Cap 1,598 cc

Power 80.0 kW (107 bhp)

Curb Weight ⓘ 1,195 kg

No. of Owners ⓘ 4

Type of Vehicle Mid-Sized Sedan

## Features

1.6L Fuel-Efficient 16 Valve DOHC VVT-i Engine, Smooth Auto Transmission With Ect, Dual SRS Airbags, ABS, Digital Climate Controls, 4x Disc Brakes. View specs of the Toyota Corolla Altis (2008-2013)

