



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS3/SMO20011737/Ktd3e2-1 Date: 09/02/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBA 9656U	Veh. Inspected	GBK 2901E
Policy No.	D20MTMC01006111	Coverage (\$)	0.00
Claim No.	CMTD2003142/AGC	Excess (\$)	0.00
Assign From	AGNES CHAN SHU HUI	Assign Date	05/02/2021
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	VM20141252	Colour	BLACK
Odometer	25216 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	165/80 R14	TOYO	5 mm
L/H Front Tyre	165/80 R14	TOYO	5 mm
R/H Rear Tyre	165/80 R14	TOYO	9 mm
L/H Rear Tyre	165/80 R14	TOYO	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/10/2020	Inspection Date	28/10/2020
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	