

Claim Handling

Task Transfer

Exit

Accident MT/1119809

LOS

SAL

SUB

Policy No.

5073023921-05

Certificate No.

Policyholder Name

BRILLIANT CORP (S) PTE LTD

Product Code

COMMERCIAL VEHICLE INSURA

Contact No.(Mobile)

NA

Email Address

KFK

No

Yes

NCD Protection

No

Vehicle No.

GBD2351D

GST Registration No.

200412598W

Policyholder NRIC

200412598W

Cover Type

Comprehensive

Loading

0

Contact No.(Office)

Contact No.(Home)

Special Remark

eCode

No

TCA

No

Yes

eCode Reason

NCD Entitlement(%)

20

Private Hire

No

Accident Details

Report Date

03/02/2021 08:53

Date of Accident

28/01/2021

Reporting Centre

NATIONAL ASSESSMENT CENTRE

Accident Location

AYE TOWARDS CITY

Accident Report Within 24 hrs

Yes

Time of Accident hh:mm

10:00

Orange Force

No

Accident Type

Chain Collision

Country of Accident

Singapore

ICM No.

4879091

Total Excess Applicable

Excess Type

Per Accident

Windscreen Excess

100.00

OD Standard Excess

600.00

YIED OD Excess

0.00

Additional Excess

Total OD Excess Applicable

600.00

TP Standard Excess

0.00

YIED TP Excess

0.00

Total TP Excess Applicable

0.00

Driver is Covered?

Not Applicable

Benefits

GST Registered Information

GST Registered

Yes

GST Registration No.

200412598W

Modification History

03/02/2021 08:57:05 System changed GST Registration Date from 01/01/2015 to 18/06/2007
03/02/2021 08:57:05 System changed GST Status Verified from No to Yes

GST Registration Date

18/06/2007

GST Status Verified

Yes

Policyholder Mailing Address

Address 1

BLK 9005 #02-262

Address 2

TAMPINES STREET 93

Address 3

SINGAPORE 528839

Address 4

Address Type

Singapore address

Post Code

528839

Unit No.

Related Policy Number

5073023921-05

OI Driver Info

Driver Name

Unnamed driver Name

Register Date of Driver License

Contact No.(Mobile)

Address 1

Address 4

Unit No.

Does he own a Singapore Registered car?

Yes

No

Driver Type

Driver NRIC

Driver Age

Contact No.(Office)

Address 2

Address Type

Foreign address

Driver Vehicle No.

Driver DOB

Driving Experience

Contact No.(Home)

Address 3

Post Code

Driver Insurer Company

Modification History

05/02/2021 22:46 s035020 Modify Orange Force(-->Y)
05/02/2021 22:46 s035020 Modify ICM No(-->4879091)

Investigation

Claim 002 OD-MD

Claim Case Officer Ng Hak Joo

Claim Type

OD-MD

Contact No.(Mobile)

90081788

Email Address

Claim Description

GBD2351D / PC8135L ON 28 Jan 2021

Preferred Workshop

Preferred

Repair Option

income to assign workshop

Insured

Claim

Fully at

Resolved

Date Registered

09/02/2021 13:47

Report Taken By

LIEW SHAN HUI

Print AK letter

☒

Modification History

Insured Name

BRILLIANT CORP (S) PTE LTD

Contact No. (Home)

OI Vehicle Number

GBD2351D

Insured NRIC

20041259

Contact No. (Office)

TP Vehicle Number

PC8135L

Name of Preferred Workshop

Claim Close Date

Workshop Repairer

Date Received

09/02/2021

Total Loss but Repaired

OD Excess Collected by Workshop

Special Claim Creation Approval

https://gicclaim.income.com.sg/gcs/icm/eclaim/damageAssessmentSave.do

1/3

2/9/2021

Claim Handling (damage assessment Claim Task MT/1119809 / Claim 002 OD-MD)

Approval

Reason

Remarks

damage assessment Attachment

Vehicle Info

Vehicle MakeNISSAN

Vehicle ModelNV200

Engine Capacity0.71

Date of Registration11/08/2014

Classis No.VSKYBAM20Z0087717

Towing Required *☒ Yes ☐ No

Vehicle in IDAC *☒ Yes ☐ No

Parallel Import *☐ Yes ☒ No

Type of Tender *Own Damage

Assessor Name *SIMON

Survey Current Status

IDAC/Workshop NameNATIONAL ASSESSMENT CENTRE

IDAC/Workshop Location51 UBI AVENUE 1 #01-25 PAYA

Windscreen Parts & Labour Cost

Total Loss *☐ Yes ☒ No

Market Value(\$)

Scrape Value(\$)

Economical Repair Value(\$)

Remark

REMARK:NO OF REPAIR DAYS:15 DAYS.2X FRT BUMPER SIDE COVER LH & RH - REPLACE.1X INTERCOOLER HOSE - REPLACE.1X AIRCON LIQUID PIPE - REPLACE.1X INTERDUCT - REPLACE.1X AIR CLEANER - REPLACE.1X ENGINE ASSY - UNCONFIRM.1X ENGINE ECU - UNCONFIRM.1X RELAY BOX - UNCONFIRM.1X FRT LH WHEEL CAP - REPLACI UNCONFIRM.1X STICKER - REPLACE.2X AIRCON CONDENSER SIDE AIR REFLECTOR - REPLACE.

Remark for Supplementary

Damage Listing					
No.	Part No.	Description	Qty *	Repair Coc	
1	32200101	NUMBER PLATE (FRONT)	1	Replace	
2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace	
3	16000101	BUMPER (FRONT)	1	Replace	
4	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	
5	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	
6	16005901	BUMPER SPONGE (FRONT)	1	Replace	
7	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace	
8	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Replace	
9	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Replace	
10	16002701	BUMPER FOG LAMP (FRONT LEFT)	1	Replace	
11	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Replace	
12	27100101	GRILLE (FRONT)	1	Replace	
13	27100801	GRILLE EMBLEM (FRONT)	1	Replace	
14	27700101	HEAD LAMP (LEFT)	1	Replace	
15	27700102	HEAD LAMP (RIGHT)	1	Replace	
16	454009	WIPER PANEL GARNISH	1	Replace	
17	45100401	WINDSCREEN GLASS (FRONT)	1	Replace	
18	45101401	WINDSCREEN MOULDING (LEFT)	1	Replace	
19	45101402	WINDSCREEN MOULDING (LOWER)	1	Replace	
20	45101403	WINDSCREEN MOULDING (RIGHT)	1	Replace	
21	45101404	WINDSCREEN MOULDING (UPPER)	1	Replace	
22	451020	WINDSCREEN SEALANT	1	Replace	
23	45101701	WINDSCREEN PILLAR (FRONT LEFT)	1	Repair	
24	245001	ERP BRACKET	1	Replace	
25	41300101	SUPPORT PANEL (FRONT)	1	Replace	
26	149001	BONNET	1	Replace	
27	14903401	BONNET LOCK (LOWER)	1	Replace	
28	14902201	BONNET HINGE (LEFT)	1	Replace	
29	14902202	BONNET HINGE (RIGHT)	1	Replace	
30	149029	BONNET INSULATOR	1	Replace	
31	112023	AIR CON CONDENSER	1	Replace	
32	112060	AIR CON FAN	1	Replace	
33	112011	AIR CON COMPRESSOR	1	Unconfirm	
34	344001	RADIATOR	1	Replace	
35	344005	RADIATOR COWLING	1	Replace	
36	344008	RADIATOR FAN	1	Replace	
37	34402802	RADIATOR HOSE (TOP)	1	Replace	
38	344007	RADIATOR EXPANSION TANK	1	Replace	

Find a Part

root

Not Applicable

ABS

ABSORBER

ACCELERATOR

ACTUATOR

ADVERTISEMENT STICKER

AIR BAG

AIR BLOWER

AIR BOX

AIR CHAMBER BOX

AIR CLEANER

AIR COMPRESSOR

AIR CON

AIR CON (VAN)

AIR COOLER

AIR DISTRIBUTOR

AIR FILTER

AIR FLOW

AIR GRILLE

AIR HORN

AIR INTAKE

AIR RESONATOR BOX

AIR THROTTLE BODY AND SENSOR

ALARM

ALTERNATOR

ALUMINIUM PANEL - SIDE

AMPLIFIER

ANTENNA

ANTI ROLL

APRON

ARCH

ARM REST

ASH TRAY

AUTO CLUTCH

AUTO COOLER PIPE

AUTO CRUISE MOTOR

AUTO TRANSMISSION

AXLE

BACK REST (M/C)

BACK SEAT

BALANCER

BATTERY

BEADING (M/C)

BELT COVER (M/C)

BELT TENSIONER

BODY

BODY (M/C)

BOLT CAP (M/C)

BOLT HEAD COVER (M/C)

BONNET

BOOT

BOX (M/C)

BOX BRACKET (M/C)

BOX CARRIER (M/C)

BOX DOOR

BOX STICKER (M/C)

BRACE PANEL

BRAKE

BRAKE - ABS

BRAKE (M/C)

BUMPER

CABIN

CAMBER

CAMSHAFT

CAR AUDIO SYSTEM

CAR JACK

CARBURATOR

CARGO

CARRIAGE

CARRIER MOUNTING

CASTOR

CATALYTIC CONVERTOR

CD CHANGER

CD PLAYER

CDI UNIT (M/C)

CENTRE BOTTOM

CENTRE BRACKET

CENTRE CONSOLE

39	141001	BATTERY	1	Replace
40	141002	BATTERY BRACKET	1	Replace
41	11001303	AIR CLEANER HOSE (TOP)	1	Replace
42	243014	ENGINE LOWER COVER	1	Replace
43	24301906	ENGINE MOUNTING (RIGHT)	1	Replace
44	19600501	CHASSIS MEMBER (FRONT LEFT)	1	Repair
45	19600502	CHASSIS MEMBER (FRONT RIGHT)	1	Repair
46	112003	AIR CON BLOWER	1	Unconfirm
47	117002	AIR FLOW METER	1	Unconfirm
48	26600101	FUSE BOX (BOTTOM)	1	Unconfirm
49	26600102	FUSE BOX (CENTRE)	1	Unconfirm
50	26600103	FUSE BOX (TOP)	1	Unconfirm
51	22600102	DASHBOARD (TOP)	1	Unconfirm
52	25400102	FENDER (FRONT LEFT)	1	Replace
53	25400801	FENDER INNER PANEL (FRONT LEFT)	1	Replace
54	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace
55	25400103	FENDER (FRONT RIGHT)	1	Repair
56	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace
57	23300201	DOOR (FRONT LEFT)	1	Repair
58	23303001	DOOR HINGE (BOTTOM) (FRONT LEFT)	1	Unconfirm
59	23303101	DOOR HINGE (UPPER) (FRONT LEFT)	1	Unconfirm
60	23306101	DOOR RUBBER (FRONT LEFT)	1	Unconfirm
61	454012	WIPER WASHER TANK	1	Unconfirm
62	124001	ALTERNATOR	1	Unconfirm
63	455001	WIRE HARNESS	1	Unconfirm

Save

Submit