

ASS. REC. BY:

REF: CS3/ASM21001791/Gvf3

Special Instruction:

Surveyor: GQ ASSIGNMENT (Office)

From (Person): CHAN KIAN CHUAN of AXA Date/Time: 5/2/2021 12:11 PM

Estimated Cost: _____ Bill to: _____

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMH 1039L Insured: SHA 8129K

at Workshop m/s APEX MOTORING Tel: 91690825

of 25 Kaki Bukit Road 4 #01-55 SYNERGY@KB

Policy No: _____ Claim No: S1M0326G

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 04-02-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: _____

Date/Time: 5-2-21 3.59P.M Person Contacted: PEI JIE Vehicle IN OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SMH 1039L- <input checked="" type="checkbox"/>
	SHA 8129K - CS/FCI17009641/T1gh3e2 DOA :15/05/2017
9/2/21	Send IA via Smart Claim
9/2/21	Submit PRS,repair range \$3,000-\$4,000 (4 days)