

ASS. BY:

REF:

CC4/LPC21001808/Dp³³

ASSIGNMENT

CJB 2025 July

From: _____ Date: _____

Estimated Cost: _____

OD / TPWS / TP RES / OD RES / EVA / INV / MV

To Insp. Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claim No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Police Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. of Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SHA2666R

Yr Regn:

July 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C.

1798

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

452682

T/Radio:

Insured / Std / NI / NA

Eng/No: -

2ZR8060088

C/No:

JTDKB3FU203562950

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

05/02/2021

D.O.I.

08/02/2021

Survey held at

Bijoy St Sin Ming

Des. of Damages: Fri / Rear / O/S / N/S / U/C / Rooftop or

Rear 4/5

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

Lumpac GBE 7215B

24/08/2021 from 2/5 7300/- with 5 days of work

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Rep. Format: _____

Lump Sum / L.B.H. (\$) _____

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)