


**ASSIGNMENT**

File No: \_\_\_\_\_ Date: \_\_\_\_\_  
 Name of Cost: \_\_\_\_\_  
 ( ) TRANSIT RES / OO RES / EVA / INV / MV  
 Inspected Vehicle No: \_\_\_\_\_  
 Odometer Reading: \_\_\_\_\_  
 Make: \_\_\_\_\_  
 Model: \_\_\_\_\_  
 Year: \_\_\_\_\_  
 Color: \_\_\_\_\_  
 Excess: **300**

Veh No: **FBR 7180Z** Yr Regn: **5 OCT 2020**  
 Type: M. Car / M. Cycle / BUS / Van / Lorry / Taxi / Private Motor /  
 Truck / Tractor or \_\_\_\_\_  
 Make: **HONDA CB 150R** cc **149**  
 Colour: **RED** NO: Insured / Std / Nil ( )  
 Sp Reading: **2,409** \*Radp: Insured / Std / Nil ( )  
 Engine: \_\_\_\_\_  
 C/C: **MHIC 9217KK023092**  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Loose / Jammed / Leaked / Burnt or  
 Brake: Loose / Jammed / Leaked / Burnt or  
 Motor: Oil / S/Rim / STD A/Rim or



Tyre Size: F: **100 180 R17**  
 R: **130 170 R17**  
 BS / BUN / EXHOVA / GY / PS / I / ZA / M / O / TS / U / R / S / U / M /  
 YO / D / Y / O / K / C or **IRC**  
 C/W: \_\_\_\_\_ mm C/W: \_\_\_\_\_ mm  
 U/W: \_\_\_\_\_ mm U/W: \_\_\_\_\_ mm  
 S/OA: **11/2021** S/O: **9/2/2021**  
 Supply Hold at: **BIKE PRODUCTION**  
 Det. of Damages: Frnt / Rear / O/S / N/S / O / Roadtrip or

Inspected by: \_\_\_\_\_  
 Date of Commencement: \_\_\_\_\_  
 Date of Completion: \_\_\_\_\_  
 Mileage at time of inspection: **10.5K**  
 Condition? Yes or No \_\_\_\_\_  
 Consistent? Yes or No \_\_\_\_\_  
 Res: Yes or No \_\_\_\_\_  
 J Val: Yes or No \_\_\_\_\_  
 Vehicle: \_\_\_\_\_  
 Vehicle: IN / OUT \_\_\_\_\_

Action / Instruction: **COE rebate \$7,074.00**  
**Repair Limit \$3K. Repairer informed.**

Days Of Repair: **3**  
 Resurvey No. of Trip: **2**  
 Survey Form: \_\_\_\_\_  
 Add Fee:  Site Insp \$5  
 Highview \$5  
 Test days \$5  
 Washing \$5

5/4/21-Typist  
 Merimen  
 LS \$2450